UNITED STATES

		budget bureau No. 42-R1424
	5.	LEASE
		SF 078422
ı	6.	IF INDIAN, ALLOTTEE OR TRIBE NAME
-		
	7.	UNIT AGREEMENT NAME
ı		
_	8.	FARM OR LEASE NAME
		Huerfano
	9.	WELL NO.
		#274
ĺ	10.	FIELD OR WILDCAT NAME
		Basin Dakota
	11.	SEC., T., R., M., OR BLK. AND SURVEY OR
		AREA
		NW Sec. 31, T-27-N, R-10-W
	12.	COUNTY OR PARISH 13. STATE
		San Juan New Mexico
	14.	API NO.
	15.	ELEVATIONS (SHOW DF, KDB, AND WD)
		6046' GL.

DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY** SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a differen reservoir. Use Form 9–331–C for such proposals.) gas well well other 2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR P.O. Box 4289, Farmington, New Mexico 87499 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 850'N, 850'W, Sec. 31, T27N, R10W AT TOP PROD. INTERVAL: a/a AT TOTAL DEPTH: a/a 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report results of multiple completio PULL OR ALTER CASING change on Form 9-330.) NOV 2 2 1983 MULTIPLE COMPLETE 1 - 1983 BUREAU OF LAND MANAGEMENT CHANGE ZONES FARMINGTON RESOURCE AREA ABANDON* (other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set retainer at approximately 6300' to shut off water.

Subsurface Safety Valve: Manu. and Type _____ Set @ 18. I hereby certify that the foregoing is true and correct Production Engineer (This space for Federal or State office use) APPROVED BY _ TITLE _ CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ZV AREA MANAGERA