

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 1336

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Thomas Jefferson

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

WAW - Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 34, T27N, R13W

12. COUNTY OR PARISH

San Juan

13. STATE

NM

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. ☐ OIL  
WELL ☐ GAS  
WELL ☒ OTHER

2. NAME OF OPERATOR

Dugan Production Corp.

3. ADDRESS OF OPERATOR

Box 234, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

900' FSL - 790' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6187' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

Completion X

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

6-3-76

Moved in and rigged up Farmington Well Service swabbing unit. Blue Jet ran gamma-ray correlation and collar log. Swabbed casing down to 800'. Perforated w/one 2-1/8" glass jet/ft 1357-1360' and 1362-1366'. Swabbed well down, very slight show gas w/no liquid. Perforated w/one 2-1/8" glass jet/ft 1346-1352'. Swabbed well, slight increase in gas, no increase in water.

6-21-76

Acidized well w/250 gals 15% HCl. BD pressure 1200 psi. Treated @ 300 psi @ 1 BPM. Flushed w/25 bbls water. Farmington Well Service swabbing unit swabbed back approx 10 bbls fluid. Well kicked off making est 150 MCFGPD.

6-22-76

Ran 42 jts 1-1/4" OD 2.3# J-55 10R reg NEUE tbg. TE 1383.89' set @ 1381' GR. Swab stop @ 1350'. Ran 1-1/4" swab one time. Well kicked off making est 125 MCFGPD. Nippled up wellhead and rigged down Farmington Well Service swabbing unit.

18. I hereby certify that the foregoing is true and correct

SIGNED

Thomas A. Dugan

TITLE

Engineer

DATE

7-8-76

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 9 1976

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

\*See Instructions on Reverse Side