Form 9-331 (Max 4983)								
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A		
OIL WELL OTHER 2. NAME OF OPERATOR Kirby Exploration Company 3. Address of Operator P.O. Box 1745, Houston, Texas 77001 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface						7. UNIT AGREEMENT NAME N/A S. FARM OR LEASE NAME Kirby Gallegos 9. WELL NO. 5 10. FIELD AND POOL, OR WILDCAT WAW Pictured Cliff 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA		
980' FSL &	980 FSL & 880 FEL 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5980 GR					Sec 26, T27N, R13W 12. COUNTY OR PARISH 13. STATE San Juan New Mexico		
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:								
proposed work.	E O OR COMPLETED If well is dir	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS OPERATIONS (Clearly state ectionally drilled, give subs	all pertinent	Completion or Rec	ompletion Repo	REPAIRING WELL ALTERING CASING ABANDONMENT* S of multiple completion on Well pletion Report and Log form.) s, including estimated date of starting any cal depths for all markers and zones perti-		
No tests ruplugging ir	rilled to un. Log c nstruction	alculations indi s from the U.S.G 75 sacks class "	cate wells.S. well	5¼" hole). Ran IE Il to be non-comme I was plugged as f nt plug from 1100-	ercial. follows: -1550 fee	After red	ogs. ceiving	
Cut 8 5/8" been fenced	Plug #3 - surface c i, locatio	10 sacks class " asing off four f	B" cemer eet belo ed and re	nt plug from 50-20 nt plug from 0-40 ow and welded cap estored to U.S.G.S -77.	feet on same.			
18. I harahy agatter	that the feature.	ng 13 true, and correct	FEE OIL	3 4 1977 CON. COM. DIST. 3	y. s.	18 18 19		

Agent

TITLE _

Jack U. Cook

2-2-77