| 6 BLM 1 File  Form 3160-5. (November 1983) (Formerly 9-331)  DEPARTMENT OF THE INTERIOR (Other Instructions on response of the supplied of the | 5. LEASE DESIGNATION AND SERIAL NO. SF 078009C   |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME   |
| OIL GAS X OTHER  | 7. UNIT AGREEMENT NAME   |
| 2. NAME OF OPERATOR  | 8. FARM OR LEASE NAME  |
| DUGAN PRODUCTION CORP.  3. ADDRESS OF OPERATOR   | 9. WELL NO.  |
| P O Box 208, Farmington, NM 87499  1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  See also space 17 below.)  At surface  | 10. FIRLD AND POOL, OR WILDCAT   |
| 77.601 44001   | Wildcat - Pictured Cliff 11. SEC., T., B., M., OR BLE, AND   |
| 1160' FNL - 1130' FWL MAY 2 4:985  | SURVEY OR ARMA   |
| BUREAU OF LAND MANAGEMENT  14. PERMIT NO.  15. ELEVATIONS (Show whether the transport of the permit no.)   | Sec. 18, T27N, R13W, NMP   |
| 6059' GL   | San Juan NM  |
| Check Appropriate Box To Indicate Nature of Notice, Report, or Co.   | Other Data   |
| NOTICE OF INTENTION TO:  | UBNT REPORT OF:  |
| TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT  | REPAIRING WELL ALTERING CASING   |
| SHOOT OR ACIDIZE ABANDON* X SHOOTING OR ACIDIZING  | ABANDONMENT*   |
|  | s of multiple completion on Well<br>letion Report and Log form.)   |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates proposed work. If well is directionally drilled, give subsurface locations and measured and true vertice nent to this work.)  Request permission to plug and abandon subject well as follows:   | al depths for all markers and zones perti-   |
| <ol> <li>Plan to fill 2-7/8" OD, 6.4# tubing for casing from P.E<br/>to surface with 37 sx of class "B" cement.</li> </ol>   | B.T.D. of 1408'  |
| 2) Plan to install permanent dry hole monument   | and the second of the second o |
| 3) Plan to fill all pits.  | MAY 311985   |
| 4) Plan to clean well location of all equipment, pipe, jur   | ik and trash.  |
| 5) Plan to restore surface.  |  |
| 6) Plan to cut off tie-downs.  |  |
| 18. I hereby certify that the foregoing is true and correct  | APPROVED   |
| SIGNED Nermans Vadagherman E. Dugarithe Geologist  | DATE 5-23-85   |
| (This space for Federal or State office use)   | MAY_2 9 1985   |
| APPROVED BY TITLECONDITIONS OF APPROVAL, IF ANY:   | John o Kalla   |
|  | FOR AREA MANAGER FARMINGTON RESOURCE AREA  |

\*See Instructions on Reverse Side