

U. S. GEOLOGICAL SURVEY
Drawer 600
Farmington, New Mexico 87499-00600

Attachment to Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: S Federal

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Bureau of Land Management for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
5. The following modifications to your plugging program are to be made (when applicable):
 - a) Spot cement inside casing from 1460' T.D. to 936' to cover Fruitland top at 986'.
 - b) Perforate 2 7/8" casing at 131' and spot cement inside and outside casing from 131' to surface to cover Ojo Alamo top at 81' and surface casing shoe at 29'.
 - c) Install dry hole marker.

Office Hours: 7:30 A.M. to 4:15 P.M.