

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R14

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	5. LEASE DESIGNATION AND SERIAL NO. NM 11580
2. NAME OF OPERATOR Dugan Production Corp.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 234, Farmington, NM 87401	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1850' FSL - 790' FEL	8. FARM OR LEASE NAME KR
14. PERMIT NO.	9. WELL NO. #9
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 6117' GR	10. FIELD AND POOL, OR WILDCAT WAW Pictured Cliff
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 19 T27N R13W
	12. COUNTY OR PARISH San Juan
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT ON:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plan to spot 20 sx cement TD (1475') to 1200'.

Plan to spot 20 sx cement 600' to 400'.

Plan to spot 10 sx cement 100' to surface.

Plan to cut off surface csg 5' below ground level and clean up loc

MAY 22 1978
OIL CON. COM.
DIST. 3

RECEIVED

MAY 18 1978

18. I hereby certify that the foregoing is true and correct

SIGNED Thomas A. Dugan
Thomas A. Dugan
(This space for Federal or State office use)TITLE Petroleum EngineerAPPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 5-15-78

DATE _____