

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form Approved,
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 0499348
2. NAME OF OPERATOR Dugan Production Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 234, Farmington, NM 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1850' FSL - 2000' FWL		8. FARM OR LEASE NAME FAF
14. PERMIT NO.		9. WELL NO. #4
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6154' GR		10. FIELD AND POOL, OR WILDCAT WAW
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 30 T27N R13W
		12. COUNTY OR PARISH San Juan
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) perf & tbq	
(Other) <input type="checkbox"/>			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *


5-4-78 Moved in and rigged up FWS swabbing unit. Blue Jet ran gamma ray correlation and collar logs. PBTD 1417'. Swabbed csg down to 1000'. Perforated w/1 2-1/8" glass jet/ft 1335-1345' (10 holes). Made one swab run. Well kicked off making estimated 150 MCFGPD. Rigged down unit and moved off.

5-8-78 Moved in and rigged up FWS swabbing unit. Ran 41 jts. 1-1/4" OD 2.3# J-55 IJ tbq. TE 1335.11' set @ 1333' GR. Landed tbq and installed master valve. Well making est. 100 MCF. Shut in. Rigged down FWS.

RECEIVED

MAY 11 1978

U. S. GEOLOGICAL SURVEY



18. I hereby certify that the foregoing is true and correct

SIGNED Thomas A. Dugan

TITLE Petroleum Engineer

DATE 5-9-78

(This space for Federal or State/office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____