Form 3160-5 (June 1990)

1 Type of Well

2 Name of Operator

TOP OT MANCOS

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	FORM	LAPPR	OVE	,
/ Bi	idget Bure	cau No	1004	0115
/	Expires:	March	31,19	93
Lease	Designat	ion and	Seria	No

JINDRY NOTICES AND REPORTS ON WELLS

NMSF-078478

6 If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE UNIT J R. Well Name and No. Well Well Other FEDERAL E5 9 API Well No BLEDSOE PETRO CORPORATION 214/742-5800 3 Address and Telephone No. 1717 MAIN STREET SUITE 5850 DALLAS TX 75201 10. Field and Pool, or Exploratory Area OTERO CHACRA 4 Location of Well (Footage, Sec., T., R., M., or Survey Description) 11 County or Parish, State 23 - T.27 N. R.8 W. SEC. 23 SAN JUAN, NEW MEXICO 1650' FSL & 1500' FEL

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION X Ahandonment Change of Plans Notice of Intent New Construction Recompletion Non-Routine Fracturing Subsequent Report Plugging Back Water Shut Off Casing Repair Conversion to Injection Altering Casing Final Abandonment Notice Dispose Water (Note Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled. give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

607' TOP OF NACIMIENTO 1399' TOP OF OJO ALAMO TOP OF KIRTLAND 1501' 1948' TOP OF FRUITLAND 2161' TOP OF PICTURED CLIFFS 2270' TOP OF LEWIS 3086' TO TD TOP OF CHACRA PLEASE SEE ATTACHED TOP OF CLIFF HOUSE FOR PROCEDURES TOP OF MENEFEE TOP OF POINT LOOKOUT

PETROLEUM ENGINEER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United State on State of St or representations as to any matter within its jurisdiction

BLEDSOE PETRO CORPORATION PLUGGING PROCEDURES FEDERAL E 5

- 1) Set CIBP @ 3031' and spot 50' of cement on top of plug
- Perf @ 1998', place cement plug from 1998' to 1898' inside and outside the casing with 100% excess cement in the annulus and an additional 50 linear feet inside the casing.
- 3) Perf @ 1551', place cement plug from 1551' to 1349' inside and outside with 100% excess in the annulus and an additional 50 linear feet inside the casing.
- 4) Perf @ 657', place cement plug from 657' to 557' inside and outside casing with 100% excess in the annulus with and 50 linear feet inside the casing.
- 5) Perf @ 235' and circulate cement to surface.