Form 3160-5 (June 1990)

representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Do not use this form for prop	OTICES AND REPORTS ON WELLS 27 M 9: 16 possils to drill or to deepen or reentry to a different reservoir. EATION FOR PERMIT - " for such proposals Attention:	SF-078390 6. If Indian, Allottee or Tribe Name
Amoco Production Company	Patty Haefele	9. API Well No.
3. Address and Telephone No. P.O. Box 800, Denver, 4. Location of Well (Footage, Sec., T., R., M., o	Survey Description)	3004524029 10. Field and Pool, or Exploratory Area Basin Dakota 11. County or Parish, State San Juan New Mexico
12. CHECK APPROPR	IATE BOX(s) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water tt results of multiple completion on Well Completion or on Report and Log form.)
subsurface locations and measured and true	(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting exertical depths for all markers and zones pertinent to this work.)* ny requests permission to workover this well per the attached	
Wayne Townsend gave ve		DECENTED APR - 1 1996
		OM COM. DIV.
14. I hereby certify that the foregoing is true and	correct I file Staff Assis	tant 03-25-1996 APPROVED
(This space for Federal or State office use) Approved by	Title	MAR-18 7 1996
Conditions of approval, if any: Title 18 U.S.C. Section 1001, makes it a crime f	or any person knowingly and willfully to make to any department or agency of the United State	

SJOET Well Work Procedure

Wellname:

Price Com 4

Version:

#1

Date:

March 22, 1996

Budget:

Repair

Workover Type:

Drill deeper, Reperf, Frac

Objectives:

Reservoir study has identified bypassed pay in the lower Dakota.

Tubing will be pulled and inspected.

2. Fill will be checked for and cleaned out if necessary.

3. PBTD will be deepened to 7324'.

Lower DK will be isolated and perf'd and frac'd 4.

Tubing will be landed at 7300' and well returned to production. 5.

Pertinent Information:

Location:

1085' FNL, 1090' FEL, 24-28N-8W

Horizon:

DK

County:

San Juan

API #:

30-045-24029

State:

New Mexico

Engr:

Mark Rothenberg W--(303)830-5612

Lease: Well Flac:

Federal # SF078390

Phone:

H--(303)841-8503

9796150 Lease Flac 698443

P--(303)553-6448

Economic Information:

APC WI:

100%

DK Prod. Before Repair:

15 MCFD

Estimated Cost:

\$40,000

DK Anticipated Prod.:

145 MCFD

Payout:

10 months

Max Cost -10 Mo. P.O.

\$40,000

NOTE: New goal of 10 month payout for all repair wells.

Formation Tops: (Estimated formation tops)

Cliffhouse:

4430

Menefee:

4680

Point Lookout:

5012

Mancos Shale: 5200

Greenhorn:

6377

Graneros: Dakota:

6700 7080 Wellname: Price Com 4

Page 2 3/22/96

Suggested Procedures:

- 1. Contact Federal or State agency prior to starting repair work.
- 2. Install and/or test anchors on location.
- 3. MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 4. Blow down well and kill well, if necessary, with 2% KCL water.
- 5. ND wellhead. NU and pressure test BOP's.
- 6. TIH and tag PBTD, check for fill. Trip and tally out of hole with tubing, checking condition of tubing. Inspect tubing for scale and/or crimping and replace joints as needed.
- 7. RIH with bit and drill from PBTD (7298') to casing shoe at 7324'. Clean well out to new PBTD.
- 8. Run GR/CCL log and correlate to Welex Gamma-Induction log ran on 8/30/80 and perforate the following intervals with 2 JSPF:

7283-7285 7295-7308

- 9. Frac down tubing according to attached frac procedure (set packer at approx. 7275').
- 10. Flow well back as soon as possible after frac., recording flowing and shut in pressures.
- 11. When sand production stops, TIH with production string, landing tubing open ending with seating nipple 1 joint off bottem at 7300'.
- 12. Swab well in and put on production.
- 13. Rig down move off service unit.

If problems are encountered, please contact:

MARK ROTHENBERG

(W) (303) 830-5612

(H) (303) 841-8503

(P) (303) 553-6448

Wellbore incorrect. Casing shoe at 7324', not 7385'.

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTICES	AND REPOR	RTS ON WELLS
-----------------------	-----------	--------------

SUNDRY NOTICE	ES AND REPORTS ON WELLS	6. Lesse Designation and Serial No.
	to drill or to deepen or reentry to a different reservoir.	SF-078390
Use "APPLICATION	N FOR PERMIT - " for such proposals	6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well		_
Oil Ges Other		
2. Name of Operator		8. Well Name and No.
Amoco Production Company	Attention:	Price Com #4
3. Address and Telephone No.	Patty Haefele	y. Art Well No.
P.O. Box, Denver, CO 802	(303) 830-4988	3004524029
4. Location of Well (Footage, Sec., T., R., M., or Survey I		10. Field and Pool, or Exploratory Area
		Basin Dakota 11. County or Parish, State
1085' FNL 1090' FEL	Sec. 24 T 28N R 8W Unit A	VI. County of Parisit, State
		San Juan New Mexico
12. CHECK APPROPRIATE	BOX(s) TO INDICATE NATURE OF NOTICE, R	EPORT OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	EL OILL, OIL OTHER DATA
	THEORACION	
	Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Subsequent report	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
	Recompletions at all pertinent details, and give pertinent dates, including estimated date of starting epiths for all markers and zones pertinent to this work to	rt results of multiple completion on Well Completion or on Report and Log form.)
total shots, .340" diameter, 3.1 7285'. Frac lower Dakota 728	Id PBTD to new PBTD of 7324'. CP 300 psi, circrorated new Dakota intervals at 7283-7285', 72 25" gun, 120 deg phasing, 12.5 gms. Set CIBP 33-7308' with 30,000 lbs 20/40 Ottawa sand, 39 up packer, circulate hole, cleanout to pbtd. Tag SU 4/8/96.	295-7308' with 2 JSPF, 30 at 7324'. Set packer at
	The second secon	
	APR 2 2 1998	
	- 2 1000	
	Contractor 2	
	WIND SEE SEE	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
	Dilitio 33	
. I hereby certify that the foregoing is true and correct		
Patty Hack	0-	••••
Signed Fury Halfe	Title Staff Assista	ont 04-10-1996
e space for Federal or State office use)		AUCEPTED FUR REGURD
Approved by Conditions of approval, if any:	Title	APR 1-9 1996
· · · · · · · · · · · · · · · · · · ·		N II 2 0 1000
a 18 U.S.C. Section 1001, makes it a crime for any person	n knowingly and willfully to make to any description	SARAHATAH MATRIAT ATTICT
esentations as to any matter within its jurisdiction.	n knowingly and willfully to make to any department or agency of the United States	*** TAMMING THE HIS HIGH OFFICE
		8Y AM