5 MMS, Fmn

1 +11e

Form Approved.

Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GFOLOGICAL SURVEY

5. LEASE	
NM 27913	

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas XX other	La Lee Ann
well Well AM other	9. WELL NO.
2. NAME OF OPERATOR	2
DUGAN PRODUCTION CORP.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	WAW FR PC
P O Box 208, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
holow)	Sec 28 T27N R13W
AT SURFACE: 990' FNL - 1650' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
	15 FEEVATIONS (SHOW DF, KDB, AND WD)
REPORT, OR OTHER DAIN	DVD - CI
SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	(NOSBRNEPORT results of multiple completion or zone OGICAL N. Mchange on Form 9-330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine Plan to plug and abandon well as follows:	HIECTIONS IN CHINEST STAGE SOUPERINGE INCOME.
Trull to prug and abandon werr as fortons.	
 Fill 2-7/8" casing with cement (37 sacks Install dry hole marker. Clean and restore location. 	OIL CON. DIV.
	DIST. 3
Subsurface Safety Valve: Manu. and Type	Set @ Ft

18. I hereby certify that the foregoing is true and correct

SIGNED TITLE Geologist DATE 1-4-83

(This space for Federal or State office use)

APPROVED
AS AMENDED

*See Instructions on Reverse Side

JAN 2 1903 January Rodin January F. SIMS DISTRICT ENGINEER