## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT - " for such proposals	5. Lease Designation and Serial No.  SF-077875  6. If Indian, Allottee or Tribe Name
	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Gas Well Other  2. Name of Operator  Attention:	8. Well Name and No. P. O. Pipkin # 4E
Amoco Production Company Lois Raeburn  3. Address and Telephone No.	9. API Well No. 3004525106
P.O. Box 800, Denver, Colorado 80201  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	10. Field and Pool, or Exploratory Area  Basin Dakota
800 FNL1.650FWL Sec. 17 T 27N R 10W	11. County or Parish, State  San Juan New Mexico
TYPE OF SUBMISSIPPE (A) TYPE OF ACTION	REPORT, OR OTHER DATA
Notice of Intent  SEP - 2 1994  Abandonment  Recompletion  Plugging Back  Casing Repair  Altering Casing  Other  (Note: Re Recompletion)	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water port results of multiple completion on Well Completion or tion Report and Log form.)
13. Describe Proposed or Complated Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of startisubsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*  Amoco Production Company request permission to Plug and Abandon the above mentioned Preapproved, Verbal Steve Mason, by Carolanne Wyett, 8/16/1994 @ 1:30 pm  If you have any questions please contact Carolaanne Wyett @ (303) 830-5578.	
14. I hereby certify that the foregoing is true and correct  Signed	sistant <sub>Date</sub> 08-24-1994
Approved by Title Conditions of approval, if any:	Date
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United Strepresentations as to any matter within its jurisdiction.	ates any falsa, ficticious, or fraudulent statements or

\* See Instructions on Reverse Side

NMOCO

DISTRICT MANAGER

AUG 16 '94 91: 97PM AMOCO 12TH	FLOOR 3038304777	F Cardanse wyett
Date / Time Sent	BLM	o apc
8/16/94 2:00 This transmission 2 pages	FAX Number	FAX Telephone Number
consists of	FAX Operator's Number for Confirmation	ts a so. Lhanka Ly
Notes: all your Melp.	Carolane	
	560 - 3067	

## PXA Procedures P.O. Pipkins 4E

- 1. RIH with tbg and CIBP, set CIBP at 4428'. Pull out of BP and set 50' of cement on top. (6.68 cuft cement)
- 2. Pull up hole and spot cement plugs at the following intervals with 50% excess, Mesa Verde at 3283' to 3183', Chacra at 2653' to 2553', Pictured Cliffs at 1693' to 1743' and Fruitland at 1345' to 1445'. (20.04 cuft cement each plug)
- 3. RIH with perf gun and shoot squeeze holes at 844' and attempt to circulate to surface with 299.282 cuft cement. Pull out and fill hole to surface with 169.138 cuft cement.
- 4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 5. Turn over to John Schwartz for reclamation.

5

6. Rehabilitate location according to BLM or State requirements.