

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☒ gas well ☐ other

2. NAME OF OPERATOR JOHN STAYER

Rm 200, 3535 - East 30th, Farmington, NM

AT SURFACE: ~~920 FWL~~ & ~~1266~~ FWL Sec 3
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>
(other)	

RECEIVED
(NOTE:
SEP 04 1986
BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

RECEIVED

SEP 04 1986

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

It is proposed to plug and abandon the well in the following manner:

1. Spot 15 sack cement plug from TD of 1381 to 1200' to cover Dakota top at 1376'.
2. Spot 12½ sack plug from 400' to 550'.
3. Spot 50' plug at surface with regulation marker.
4. Remove surface equipment and restore.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Agent DATE 9-3-86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

SEP 12 1986

OIL CON. DIV.
DIST. 2
INSTRUCTIONS ON REVERSE SIDE

*See Instructions on Reverse Side

NMOCC

APPROX. 100

~~SEP 1 1 1986~~

FARMING FOR THE FUTURE