

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.  
I-89-Ind-57

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

John Staver

3. ADDRESS OF OPERATOR % Pohlmann & Assoc., Room 200  
3535 E. 30th, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface 1984' FNL & 724' FWL sec 3

920/N 1268/W

RECEIVED

14. PERMIT NO.

NOV 21 1986

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5369' GL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Table Mesa

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

Table Mesa Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 3, T27N, R17W

12. COUNTY OR PARISH

San Juan

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugged & Abandoned as follows:

1. Spot 15 sack plug from TD 1381' to 1200'.
2. Spot 12½ sack cement plug from 400' to 550'.
3. Spot 50' cement plug from surface with regulation marker.
4. Cleaned and restored location.

Approved as to plugging of the well bore.  
Liability under Bureau of Land Management  
surface restoration is complete.

OIL CORP. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

11-20-86

DATE

NOV 23 1986

\*See Instructions on Reverse Side