PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON*

SHOOT OR ACIDIZE REPAIR WELL

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

orm 9–331	Budget Bureau (10: 42 11-12)
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE NM-04202
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON	WELLS 7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
reservoir, use roini 3-332-3 to describe the second	Jackson Com
1. oil gas	9. WELL NO.
well	1
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
Tenneco Oil Company	Basin Dakota
3. ADDRESS OF OPERATOR Box 3249, Englewood, CO 80155	-11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. S	ee space 17 AREA
E -tana S	
AT SURFACE: 400' FSL, 1790' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan NM
AT TOTAL DEPTH:	14. APT NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE	OF NOTICE, ELEVATIONS (SHOW DF, KDB, AND WD)
REPORT, OR OTHER DATA	
REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT TEST WATER SHUT-OFF FRACTURE TREAT	1982 GRIVEY
TEST WATER SHUT-OFF FRACTURE TREAT	NOV 1
SHOOT OR ACIDIZE	NO . CALLE M

change on Form 9-330.)

(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11/10/82: RIH w/2-3/8" tbg, sn 1 jt off btm, tag sd @ 7390; CO to PBTD w/foam.

Land tbg @ 7412'. NDWH, NUBOP. Kicked well around w/N2. Left FTCU.

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct Production AnalystoAte November 15, 1982 (This space for Federal or State office use) ACCEPTED FOR RECORD

: NOV 24 1982

FARMANGTON DISTBUM