

1 Southland Royalty 1 File
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		3. LEASE DESIGNATION AND SERIAL NO. NM 33024	
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 208, Farmington, NM 87499		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790' FNL - 1850' FEL		8. FARM OR LEASE NAME Kennebec	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DV, RT, GL, etc.) 5912' GL		10. FIELD AND POOL, OR WILDCAT WAW Fruitland PC	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 32, T27N, R12W, NMPM	
		12. COUNTY OR PARISH San Juan	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plan to plug and abandon well as follows:

1. Fill 2-7/8" tubing with cement.
2. Install dry hole marker.
3. Restore location.

RECEIVED
FEB 23 1988
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct		DATE 2-16-88	
SIGNED <u>Jim L. Jacobs</u>	TITLE <u>Geologist</u>	DATE <u>FEB 23 1988</u>	
(This space for Federal or State office use)		DATE <u>Feb 23 1988</u>	
APPROVED BY <u>Jim L. Jacobs</u>	TITLE <u>Geologist</u>	DATE <u>Feb 23 1988</u>	
CONDITIONS OF APPROVAL, IF ANY:		DATE <u>Feb 23 1988</u>	

*See Instructions on Reverse Side