Form approved

	ember 1983) UNITED STATES SCHAFF IN TRIPICATE		Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. NM-013861	
SUNDRY N (Do not use this form for the "AP"	OTICES AND REPORTS Corposals to drill or to deepen or plug be PLICATION FOR PERMIT—" for such pr	ON WELLS	6. IF INDIAN, ALLOTTE	
OIL GAS WELL OTH	ER		7. UNIT AGREEMENT N	aka Al
2. NAME OF OPERATOR KOCH EXPLORATION COMPANY			8. FARM OR LEASE NAME Dryden 9. WELL NO.	
3. ADDRESS OF OPERATOR				
P.O. Box 2256	6, Wichita, KS 67201			
4. LOCATION OF WELL (Report locat See also space 17 below.) At surface	ion clearly and in accordance with any	State requirements.*	1-E 10. FIELD AND POOL, O Basin Dak 11. SEC., T., E., M., OR I SURVEY OR ARKA	ota
1300' FNL & 555' FEL (NE NE)			Sec. 28-28N-8	W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF.	RT, GR, etc.)	12. COUNTY OR PARISH	1 13. STATE
NA	GR 6255', KB 6267.	5'	San Juan	New Mexico
	Appropriate Box To Indicate N	• • •	Other Data	
TEST WATER SHUT-OFF FRACTURE TREAT 8HOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETE Droposed work. If well is di	MULTIPLE COMPLETE  ABANDON® CHANGE PLANS  O OPERATIONS (Clearly state all pertinent rectionally drilled, give subsurface locations)	Completion or Recomple	of multiple completion etion Report and Log for	on Well
Drilled 9-7/8 casing. Set Plug down at	B" hole from 218' to 2870 casing at 2870', cemente 10:05 P.M., 6-24-84. Heat circulate to surface.	0'. Ran 71 jts 7-5/8 ed w/400 sx lite & 10	26.4# K-55 ST 0 sx class "B"	&C
	Yanga da	e e e e e e e e e e e e e e e e e e e	RECEIV	ED

JUL -2 1984

JUL 13 1064

BUREAU OF LAND MANAGEMENT FARMINGTON PESOURCE AREA

BY.....

OIL CON. DIV.

SIGNED Owall L. Schmist	ritle Vice President-Prod	d/Oper 6/26/94
O.L. Schmidt	TITLE VICE FIESTGERE FICE	d/Oper. DATE 6/26/84
(This space for Federal or State office use)		ACCEPTED FOR RECORD
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	•	JUL 1 2 1984
	MOCC	JUL 1 2 1304
	See Instructions on Reverse Side	FARMINGIUN RESUURCE AREA
·	See Instructions on Reverse Side	Smm