UNITED STATES

DEPARTMENT OF THE INTERIOR RECEIVED BUREAU OF LAND MANAGEMENT REPRESENTED

Sundry Notices and Repor	S on Wells AM 7: 48	- 	
1. Type of Well GAS	070 FARMINGTON, NA	5.	Lease Number NM-02861 If Indian, All. or Tribe Name
		7.	Unit Agreement Name
2. Name of Operator MERIDIAN OIL			
	<u> </u>	8.	Well Name & Number
3. Address & Phone No. of Operator	326-9700	9.	Lodewick #12 API Well No.
PO Box 4289, Farmington, NM 87499 (505)	320-3700	J.	30-045-27716
4. Location of Well, Footage, Sec., T, R, M 1675'FNL, 1500'FEL, Sec.19, T-27-N, R-9-W,	MMPM	10.	Field and Pool Basin Fruitland Coal
16/5 FNL, 1500 FEL, Sec. 19, 1-27-N, R-9-W,	MATERI	11.	County and State
			San Juan Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE	ב אַרַתַרָב בּבַּרַרָּ	OTHER	ПАТА
	ype of Action	OTHER	Data
X Notice of Intent Abandonm	ent Change		
Recomple			
Subsequent Report Plugging Casing R	Back Non-Rome epair Water :		
Final Abandonment Altering	Casing Conver		
	Pay add		
13. Describe Proposed or Completed Operatio			
It is intended to add pay to the Fruitl fracture treat according to the	and Coal formation	of th	e subject well and
fracture treat according to the	accached procedure	· •	
	l ²	GA	
	U	I IS W	
		MAY	- 4 100m LV
		MAI	4 1000
	(0)	ML C	on. div.
	· ·		Oldo del 05 ISI. 3
			rano 0
14 I hereby certify that the foregoing is	true and correct.		
Signed Many Hadhild (PMP1) Title		<u>s</u> Da	te 4/19/95
(This space for Federal or State Office use)			
APPROVED BY Title _ CONDITION OF APPROVAL, if any:		ate _	DDDAVET
COMPTITION OF AFTINOVIED, IT any.		•	IPPROVED

NMOCD

APR 25 1995 DISTRICT MANAGER

Lodewick #12 FRTC Completion Procedure G 19 27 9 San Juan County, N.M.

- Comply to all NMOCD, BLM, & MOI rules & regulations. MOL and RU completion rig. NU 6" 900 series BOP with flow tee and stripping head.
 NU blooie line and 2-7/8" relief line.
- 2. Set blanking plug in S.N. of 2-3/8" tbg @ 2221' & pressure test to 3000 psi. Lower tbg to tag fill. If fill is above 2230', C.O. w/air/mist to 2365'. TOH w/ 71 Jts 2-3/8" tbg.
- 3. Spot and fill 2 400 bbl. frac tanks with 2% KCL water. Filter all water to 25 microns. One tank is for gel & one tank for breakdown water. Usable water required for frac is 289 bbls.
- 4. Perf additional FRTC 2316'-22' w/4 spf. Perforate using 3-1/8" hollow steel carrier guns loaded w/Owen HSC 13 gm. charges phased at 90 degrees & 4 spf. Avg. perf dia.= 0.48". Average penetration is 18" in Berea. Total 24 holes.
- 5. TIH with 4-1/2" PKR on 2-3/8" tbg & set @ 2300'. Breakdown & attempt to balloff perfs 2316'-2322' w/1500 gal. 15% HCL & 60 -7/8" 1.3 sp gr RCN perf balls. (1 gal/1000 corrosion inhibitor). Record breakdown pressures. TOH.
- 6. Run 4-1/2" straddle pkrs on 2-7/8" NUE N-80 rental tbg w/shaved collars. Spot 3 bbls 60# gel from 2300'-2150'. Set compression pkr @ 2300' & snap-set pkr @ 2150'.
- 7. Fracture treat well down frac string with 39,000 gals. of 70 quality foam using 30# gel as the base fluid & 60,000# 20/40 Arizona sand. Pump at 40 BPM. Monitor bottomhole and surface treating pressures, rate, foam quality, & sand concentration with computer van. Sand to be tagged with 0.4 mCi/1000# Ir-192 tracer. Max. pressure is 6000 psi and estimated treating pressure is 4500 psi. Treat per the following schedule:

<u>Stage</u>	Foam Vol. (Gals.)	Gel Vol.	Sand Vol.
Pad 1.0 ppg 2.0 ppg 3.0 ppg 4.0 ppg Flush Totals	10,000 10,000 10,000 6,000 3,000 (1,508) 39,000	3,000 3,000 3,000 1,800 900 (452)	10,000 20,000 18,000 12,000

LODEWICK #12 FRTC - PERF & FRAC BASAL COAL Page 2

Shut well in after frac for six hours in an attempt to allow the gel to break. Treat frac fluid with the following additives per 1000 gallons:

- (Guar Gel mix in full tank 16,000 gal) 30# J-48
- * 1.0 gal. Aqua Flow (Non-ionic Surfactant mix in full tank)
- (Enzyme Breaker mix on fly) * 1.0# GVW3
- (Breaker mix on fly) * 1.0# B-5
- * 5.0 gal Fracfoam I (Foamer mix on fly)
 * 0.38# FracCide 20 (Bacteriacide mix in full tank)
- Open well through choke manifold and monitor flow. Flow @ 20 bbl/hr, 8. or less if sand is observed. Take pitot gauges when possible.
- TOH w/frac string. TIH with 3-7/8" bit on 2-3/8" tbg and clean out to 9. 2365' w/air-mist.
- 10. Monitor gas and water returns and take pitot gauges when possible.
- When wellbore is sufficiently clean, TOH and run after frac gamma-ray 11. log from 2365'-2000'.
- TIH with 2-3/8" tbg with standard seating nipple one joint off bottom 12. and again cleanout to 2365'. When wellbore is sufficiently clean, land tbg at 2250'KB. Take final water and gas samples & rates.
- 13. ND BOP and NU wellhead & tree. Rig down & release rig.

Approve:	
	Drilling Superintendent

VENDORS:


Wireline:	Basin	327-5244
Fracturing:	Western	327-6222
RA Tagging:	Pro-Technics	326-7133
Packer:	Schlum	325-5006

LODEWICK #12 FRTC

RECEIVED BLM 95 APR 25 AM 7: 48 070 FARMINGTON, NM

UNIT G SECTION 19 T27N R9W SAN JUAN COUNTY, NEW MEXICO

4-1/2" @ 2369" _ CIRC 30 SX CMT



Pertinent Data Sheet - LODEWICK #12 FRTC

Location: 1675'FNL 1500' FEL SEC. 19 T27N R09W, SAN JUAN COUNTY, N.M.

Field: Basin Fruitland Coal Elevation: 6465' TD: 2370'

Prop#: 012619703

Lease: Federal NM-02861

DP#: 20861A GWI: 100% NRI: 83.675518%

Completed: 7-15-90

.

Initial Potential:

Pitot= 45 MCF/D

Casing Record:

Hole Size	Csq. Size	Wt. 8	<u>Grade</u>	Depth Se	et <u>Cement</u>	Top/Cmt
12-1/4"	8-5/8"	20#	X-42	226'	250 sx	Circ 104 sx Cmt
7-7/8"	4-1/2"	11.6#	J-55	2369'	150 sx	Circ 30 sx Cmt
, -	,		DV Tool	@ 1935'	650 sx	Circ 150 sx Cmt
Tubing Reco	<u>rd:</u> 2-3/8"	4.7#	J-55 SN	2222' @ 2221'	71 Jts (Notched Coll	ar on bottom)

Formation Tops:

Ojo Alamo 1486'
Kirtland 1548'
Fruitland 2122'
Pictured Cliffs 2322'

Logging Record: Density, Microlog, coal analysis

<u>Stimulation:</u> Perfed FRTC @ 2279-90', 2241'44', 2234'-37', 2222'-26', 2218', 2209'-12, 2202'-05' w/4 spf. Total 136 holes. Fraced w/204,000# sand in 30# X-linked gel.

Workover History: None

<u>Production History:</u> First delivered 9-90. SBHP = 455 PSI @ 2005'. Current capacity is 83 MCF/D @ a line pressure of 150 psi. Acquired from Unical 2/1/93.

Pipeline: EPNG

PMP