Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

5. Lease Serial No.

NMSF-07887	2Δ	L
------------	----	---

6. If Indian, Allottee or Tribe Name

					N/A		
SUBMIT IN TRIPLICATE - Other instructions on reverse side		7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well							
	Other			8. Well Nam	ne and No.		
Name of Operator	HOM OU COMBAN			BC	DLACK 15 2 E		
	HON OIL COMPANY			9. API Well			
1.0. DOX 3	552 TX 79702-0552	1 '	No. (include area code) 1915) 687-8357		30-045-30423		
	., T., R., M., or Survey Description		7-0001	10. Field and Pool, or Exploratory Area BASIN DAKOTA			
SURFACE: NEN' BHL: SAME	W SEC 15, T27N, R	11W, 1100' FNL	& 1650' FWL		or Parish, State JUAN COUNT	ΓΥ, NΜ	
12. CHECK AF	PPROPRIATE BOX(ES) TO	O INDICATE NATUR	E OF NOTICE, RE	EPORT, OR	OTHER DATA		
TYPE OF SUBMISSION		TY	PE OF ACTION				
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (Star	t/Resume)	Water Shut-Off Well Integrity		
Subsequent Report	Change Plans	Plug and Abandon	Recomplete Temporarily Ab	andon	Other		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	aison			
If the proposal is to deepen dire Attach the Bond under which the following completion of the invitesting has been completed. Fi determined that the site is ready	ectionally or recomplete horizonta he work will be performed or pro volved operations. If the operation inal Abandonment Notices shall	ally, give subsurface location ovide the Bond No. on file on results in a multiple come be filed only after all requi	with BLM/BIA. Requipletion or recompletion irrements, including recli	ired subsequer in a new inter amation, have	nt reports shall be filed rval, a Form 3160-4 sha been completed, and th	within 30 o	
Attach the Bond under which it following completion of the investing has been completed. Fidetermined that the site is ready	ectionally or recomplete horizonta the work will be performed or pro- volved operations. If the operation inal Abandonment Notices shall be for final inspection.)	ally, give subsurface location ovide the Bond No. on file on results in a multiple complete filed only after all requirements.	with BLM/BIA. Requipletion or recompletion irements, including reclification of the second sec	ired subsequer in a new inter amation, have	nt reports shall be filed rval, a Form 3160-4 sha been completed, and th	within 30 o	
If the proposal is to deepen dire Attach the Bond under which it following completion of the investing has been completed. Fidetermined that the site is ready ASK THA ASK THA I hereby certify that the foregoin Name (Printed/Typed)	ng is true and correct	ally, give subsurface location ovide the Bond No. on file on results in a multiple complete filed only after all requirements.	with BLM/BIA. Requipletion or recompletion irements, including reclience.	ired subsequer in a new inter amation, have	nt reports shall be filed real, a Form 3160-4 shall been completed, and the LYEAR.	within 30 o	
If the proposal is to deepen dire Attach the Bond under which it following completion of the investing has been completed. Fidetermined that the site is ready ASK THA ASK THA I hereby certify that the foregoin Name (Printed/Typed)	ectionally or recomplete horizonts the work will be performed or provolved operations. If the operation in the operation of the operation in t	ally, give subsurface location ovide the Bond No. on file on results in a multiple complete filed only after all requirements.	with BLM/BIA. Requipletion or recompletion irements, including reclience.	or MARA	at reports shall be filed real, a Form 3160-4 shall been completed, and the LYEAR.	within 30 : Il be filed :	
Attach the Bond under which the following completion of the intesting has been completed. Fit determined that the site is ready ASK THAT ASK THA	ng is true and correct	ally, give subsurface location ovide the Bond No. on file on results in a multiple combe filed only after all requirements of the subsurface of the subsurfa	with BLM/BIA. Requipletion or recompletion irements, including reclification in the second se	or MARA	at reports shall be filed real, a Form 3160-4 shall been completed, and the LYEAR.	within 30 o	
Attach the Bond under which the following completion of the investing has been completed. Find testing has been completed. Find testing has been completed. Find the site is ready ASK THAT ASK TH	ectionally or recomplete horizonta he work will be performed or provolved operations. If the operation in th	ally, give subsurface location ovide the Bond No. on file on results in a multiple combe filed only after all requirements of the subsurface of the subsurfa	consultant	or MARA	at reports shall be filed real, a Form 3160-4 shall been completed, and the LYEAR.	within 30 o	
Attach the Bond under which the following completion of the investing has been completed. Find testing has been completed. Find testing has been completed. Find the site is ready ASK THAT ASK TH	ectionally or recomplete horizonta he work will be performed or provolved operations. If the operation in th	BE RENEWED F BE RENEWED F Title Date FOR FEDERAL OR ST	consultant	C: MAR	at reports shall be filed real, a Form 3160-4 shall been completed, and the LYEAR.	within 30 of the operator	