Form 3160-5 (June 1990)

representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED			
Budget Bureau No. 1004-0135			
Expires: March 31 1993			

BUREAU OF			
SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Designation and Serial No.	
	SF 077111		
· · ·	odrill or to deepen or reentry to a different reservoir FOR PERMIT - " for such proposals	6. If Indian, Allottee or Tribe Name	
		7. If Unit or CA, Agreement Designation	
1. Type of Well Oil Gas		8. Well Name and No.	
Well Well Other 2. Name of Operator	Attention:	Storey C LS # 1	
Amoco Production Company	Lois Raeburn	9. API Well No.	
3. Address and Telephone No.		Aztec Pictures Cliffs	
P.O. Box 800, Denver, Colorado 8020	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey De	3004507248		
800 FSL 1683 FEL	11. County or Parish, State		
		San Juan New M	exico
CHECK APPROPRIATE I	BOX(s) TO INDICATE NATURE OF NO	TICE , REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF A		
	_		
Notice of Intent	Abandonment	Change of Plans	
Notice of Intent	Recompletion	New Construction	
Subsequent Report	Plugging Back Casing Repair	Non-Routine Fracturing Water Shut-Off	
	Altering Casing	Conversion to Injection	
Final Abandonment Notice	Other	Dispose Water	
		(Note: Report results of multiple completion on Well Completion Recompletion Report and Log form.)	or
subsurface locations and measured and true vertical de	t permission to Plug $\mathcal{B}\mathcal{A}$ (), the Aztec Pi		
See attachd procedures			
If you should have any questions ple	Pase contact Mike Kutas @ (303) 8305159	RECEIVED 94 JUL 29 PM 1: 41 070 FARMINGTON, NM 001. DIV.	
4. I hereby certify that the foregoing is true and correct)	DI Company of the Com	ness Assistant Date 07-27-19	
Signed Jas F Jacobs	Title Busin	Date	
This space for Federal or State office use)		ADDDOUGO	
Account by	Title	APPROVED	
Approved by Conditions of approval, if any:	11,100	AUG n 1 1004	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United Stays any random within its jurisdiction

PXA Procedures Storey C LS #1 Pictures Cliffs only

- Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with 2% KCL water. NDWH. NUBOP.
- 3. POOH with 1 1/4" tbg. RIH with 2 3/8" workstring and retainer. Set retainer at 3162'. Squeeze perfs at 3212' to 3248' with 32.925 cuft cement. Pull out of retainer.
- 4. Test casing integrity to 500#. Isolate casing leaks and report findings to Carolanne Wyett, 5578 or Mike Kutas, 5159 in Denver for further instructions.

STOREY C LS 001
Location — 220— 28N— 9W
SINGLE PC
Orig.Completion — 11/56
Last File Update — 1/89 by DDM

