STATE OF NEW MEXICO ENERGY and MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

Page 1 Revised 10/01/78

This form is not to be used for reporting packer leakage tests in Southeast New Mexico

NORTHWEST NEW MEXICO PACKER LEAKAGE TEST

)perator	1411	RUS EXI	DIORATICAL I	//5/1+ Lease _	ZHUBRY		Well /S	
						County 5.T		
NAME OF RESERVOIR OR POOL			TYPE OF P	TYPE OF PROD. (Oil or Gas)		PROD. MEDIUM (Tog. or Cag.)		
Upper PintiRF Cliff			7 :	GHS		Flow.	C.59	
Lower	rer D + // /		·	GAS		=/ou	TubiNg	
				OW SHUT-IN P	RESSURE DAT		Stabilized? (Yes or No)	
	Hour, date shut-in 17.45 7-14-98		1.27	Langth of time shut-in		1		
	Hour, date shi	7-14-98	Length of time shu	ıt-in	55 81 press, jielg 242		Stabilized? (Yea or No)	
- Comprehensi	<u>(1,7,5) </u>	7 7 1 10		FLOW TEST				
Consmenced	at thour, date	1+11:45 7-	17-93		Zone producing	(Upper or Lower): ∠	CUCK	
Til (hour,	ME dete)	LAPSED TIME SINGE#	PRES Upper Completion	SURE Lower Completion	PRC D. ZONE		REMARKS	
14:40	7-15:78	27	35	115		DAKetn	DAKetH FleuiNo	
	7-1998	, 3 7	150	75		TURNED	CN PO	
							?	
						1/2	CEIVED	
				•				
-						Spp	GON. DIV	
Producti	on rate di	ring test		•		5/ G (Som DIA	
Oil:		ВОР	D based on	Bbls. i	n Ho	urs C	Grav GOR	
G25:				PD; Tested thr	1 (Orifice or Mo	eter):		
		•		EST SHUT-IN F	RESSUILE DAT	'A		
Upper Hour, date shul-in - Length of U			- Length of time sh	nut-in SI press. psig		-	Stabilized? (Yes or No)	
Lower Completion	Lower Hour, date shut-in		Length of time sh	Length of time shut-in			Stabilized? (Yes or No)	

FLOW TEST NO. 2

TME	LAPSED TIME SINCE ##	PRESSURE			ar ar casas	
(hour, date)		Upper Completion	Lower Completion	PROD. ZONE TEMP.	REMARKS	
						
						
Production rate di						
Oil:	BOPE	based on	Bbls. in	Uone	Grav GOR	
Gas:	•	MCER	D. Tanal d		GOR	
lemarks:		MCFF	D: Iested thru (Ortrice or Meter):		
hereby certify tha	it the information	n herein containe	d is true and com	plete to the best	of my knowledge.	
pproved	JUL 2.9	199A			RUS ExploRATION USH	
1 A	Conservation Div	vision	_		CAPICKITICN USH	
, Charle			Ву	<u> </u>	Wolle-	
itle DEPUTY O	1 a gas inspects	en ten m	Tit	le <u>Sense</u>	Operator	
itle					18	
3 • 3		:				

NORTHWEST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been distructed. Tests shall also be taken at any time that communication is suspected or when requested by the Division.

neneed at theur, date) ##

- At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Division in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- 5. Following completion of Flow Test No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.
- Flow Text'No. 2 shall be conducted even though no leak was indicated during Flow Text No. 1. Procedure for Flow Text No. 2 is to be the same as for Flow Text No. 1 except

- that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.
- 7. Pressures for gas-zone tests must be measured on each zone with a deadweight pressure gauge at time intervals as follows: 3 hours tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.

24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Division on Northwest New Mexico Packet Leskage Test Form Revised 10-01-78 with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only).