

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.

NMSF - 078904

6. If Indian, Allottee or tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

8. Well Name and No.

GALLEGOS CANYON UNIT 14

2. Name of Operator

BP AMERICA PRODUCTION COMPANY

9. API Well No.

30-045-07101

3a. Address

P.O. BOX 3092 HOUSTON, TX 77253

ATTN: C. HLAVA

3b. Phone No. (include area code)

281-366-4081

10. Field and Pool, or Exploratory Area

FC & PICTURED CLIFFS

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec. 26 T28N R12W SWSW 660' FSL 660' FWL

11. County or Parish, State

SAN JUAN COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

4/9/02 - 4/11/02. Witnessed by Ron Snow. RD WH, NU BOP. Strapped tbg out of hole. RIH with gauge ring to 1530'. Set CIBP at 1514'. RIH open ended. Loaded hole and tested to 500 psi - held good. Plug #1 1514' - 1194', 63 sxs. LD tbg to 556'. 1/2 bpm @ 600 psi. TIH with CICR and set at 493'. Plug #2: 530' - 380', 116 sxs, 76 sxs below CICR, 49 sxs above. TOOH. Perfed @ 136'. Could not establish circulation. Plug #3: 136' - surface, 46 sxs. RD BOP, Cut off WH, installed DH marker.

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title

Regulatory Analyst

Signature

Cherry Hlava

Date April 22, 2002

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

4 0 2 2002

FAR

SW FIELD OFFICE