

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

SF-077966

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Gallegos Canyon Unit

8. FARM OR LEASE NAME

Gallup Part. Area "C"

9. WELL NO.

116

10. FIELD AND POOL, OR WILDCAT

Cha Cha Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 24-T28N-R13W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Amoco Production Company - operator

Aztec Oil & Gas Company - sub operator

3. ADDRESS OF OPERATOR

AMOCO - Security Life Bldg, Denver, Colorado 80202

Aztec - 2000 First National Bank Bldg, Dallas, Texas 75202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1830' SL, 1830' WL, Section 24-28N-13W

Unit Letter K

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, or other)

5751 KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Status: 8-5/8" surface pipe to 213'. Base Ojo Alamo estimated 203'. DV tool 1668' Perforations 5435-40'. 4-1/2" casing in 7-7/8" hole. Depleted oil well.

Propose to plug well as follows:

1. Fill hole with gel-mud. Place 10 sxs. cement (130') plug from 5440 to 5310.
2. Place 10 sxs. cement (130') plug from 1733' to 1603'
3. Cut 4-1/2" casing at free point (top of annular cement calculated 430') and pull same. Fill hole with gel-mud. Place 30 sxs. cement (160') plug bottomed 75' below casing cut.
4. Place 30 sxs. cement (100') plug from 263' to 163'
5. Place 10 sxs. cement (37') plug in top of surface pipe.
6. Cut off pipe at bottom of cellar, place one sack cement on top of pipe and install regulation marker.
7. Clean up and level location to as near original contour as practicable.

AMOCO PRODUCTION COMPANY

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side