Form 3160-5 (December 1989)

UNITED STATES						
DEPARTMENT OF THE INTERIOR						
RUREAU OF LAND MANAGEMENT						

FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990

5. Lease Designation and Serial No.

SF	_	0	7	8	1	0	6
_,		v		·		v	v

SUNDRY NOTICES A	SF - 078106			
Do not use this form for proposals to drill Use "APPLICATION FOR	6. If Indian. Allottee or Tribe Name			
SUBMIT	7 If Unit or CA. Agreement Designation			
1. Type of Well OIL OIL OTI	von.	8 Well Name and No.		
WELL WELL OIR	Gallegos Canyon Unit 209			
2. Name of Operator	Mary Corley	9. API Well No.		
Amoco Production Company	30-045-11588			
3. Address and Telephone No.	10. Field and Pool, or Exploratory Area			
P.O. Box 3092 Houston, TX 77253				
4. Location of Well (Footage, Sec., T., R., M., or Survey	Description)	Basin Fruitland Coal 11. County or Parish, State		
1800' FSL 1450' FWL Sec.	15 T28N R12W Unit K	San Juan New Mexico		
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACT			
	Abandonment	Change of Plans		
Notice of Intent	Recompletion	New Construction		
Subsequent Report	Plugging Back	Non-Routine Fracturing		
Final Abandonment Notice	Casing Repair	Water Shut-Off		
.4	Altering Casing	Conversion to Injection		
	Other BLM Letter 11/15/199	9		
	(Note: Report results of multip Recompletion Report and Log	e completion on Well Completion or		
work. If well is directionally drilled, give subsurfa As per our original sundry notices, a well to properly abandon the Dakota Fruitland zone to isolate the lower sethe Fruitland. This bridge plug is integrated order to properly place cement plugs.	arly state all pertinent details, and give pertinent dates, included locations and measured and true vertical depths for all massive locations and measured and true vertical depths for all massive locations. During the recompletion, a second legment of casing from the pressures encountered to be temporary and will be drilled out to across the Gallup and Mesaverde zones for ion to leave both the Gallup and Mesaverde zones wellbore.	above the Dakota in the subject oridge plug was set below the ered during fracture stimulation of upon depletion of the Fruitland in the ultimate abandonment of the		
14. I hereby certificate the foregoing is the and correctly signed	Title Sr. Business Analyst	Date12/09/99		
(This space for Federal or State office use)				
Approved by	Title	Date		
Conditions of approval, if any:		FOR RECORE		
	DEC [1 4 1999			
Title 18 U.S.C. Section 1001, makes it a crime for any or fraudulent statements or representations as to any ma	person knowingly and willfully to make to any department or tter within its jurisdiction.			