




STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE



**BRUCE KING**  
GOVERNOR

**ANITA LOCKWOOD**  
CABINET SECRETARY

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

August 24, 1992

Mr. Robert G. Glesher  
Phillips Petroleum Company  
5525 Hwy 64, NBU 3004  
Farmington, NM 87401

RE: Temporarily Abandoned Wells

Dear Mr. Glesher:

Thank you for responding to Memorandum (3-91-10) dated December 27, 1991, however, you failed to submit the plans to bring the attached list of wells into compliance that were to be in this office by June 30, 1992. These wells are still inactive and require P&A or TA approval under Rules 201, 202 and 203. Your failure to respond will result in violation of Rule 201. If you do not respond by October 1, 1992, we may assess fines or take other appropriate measures.

Sincerely,

*Dianna K. Fairhurst*

Dianna K. Fairhurst  
Deputy Oil & Gas Inspector

XC: TA File  
DKF File  
**Well File**

## **Phillips Petroleum Company**

<b>San Juan 29-5 #45</b>	<b>A-22-29N-05W</b>
<b>San Juan 29-5 #39</b>	<b>M-23-29N-05W</b>
<b>San Juan 29-5 #88</b>	<b>G-34-29N-05W</b>
<b>San Juan 29-5 #89</b>	<b>K-34-29N-05W</b>
<b>San Juan 29-6 #78</b>	<b>L-22-29N-06W</b>
<b>San Juan 29-6 #76</b>	<b>N-23-29N-06W</b>
<b>San Juan 29-6 #85</b>	<b>A-27-29N-06W</b>
<b>San Juan 30-5 #8</b>	<b>B-11-30N-05W</b>
<b>San Juan 30-5 #104</b>	<b>G-13-30N-05W</b>
<b>San Juan 30-5 #102</b>	<b>A-26-30N-05W</b>
<b>San Juan 32-7 #5</b>	<b>H-08-31N-07W</b>
<b>San Juan 32-8 #5</b>	<b>N-10-31N-08W</b>
<b>San Juan 32-8 #23</b>	<b>N-14-31N-08W</b>
<b>San Juan 32-8 #28</b>	<b>G-16-31N-08W</b>
<b>San Juan 32-8 #1</b>	<b>G-23-31N-08W</b>
<b>San Juan 32-8 #10</b>	<b>H-24-31N-08W</b>
<b>San Juan 32-7 #3</b>	<b>A-18-32N-07W</b>