AREA 640 ACRES

## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## WELL RECORD

Mail to District Office, Oil Conservation Commission, to which Form C-101 was sent not later than twenty days after completion of well. Follow instructions in Rules and Regulations of the Commission. Submit in QUINTUPLICATE.

				•			) <b>-6</b>
	-						<b>6</b> , NMP
							Cour
Section	3	If S	state Land the Oil ar	nd Gas Lease No.	is		
illing Com	menced	tober 12	·	19 <b>53</b> . Drillin	g was Completed	Jesanber 1.	<b>2,</b> , 19 <b>5</b> ,
me of Dri	lling Contrac	tor	t stem ir	Lllin Com	<b></b>	•	•
ldress	. v. 30x	191, 1984	reck, Texas			***************************************	
							be kept confidential un
,		•••••	, 19				
			oı	L SANDS OR Z	ONES		
. 1, from		t	·o33. Ø	No. 4	, from	]to	5178
- ·							
							5574
•	7,750				5574	•	5702
				RTANT WATER			
			l elevation to which			foot	OFILER
	-					feetfeet.	// .W \ \ \ \ \
			to				N Pro Colo
			to				WER CHI C
o. 4, from			to			Ieet	OIL DIET.
				CASING RECO	RD		Dia.
				CHSMIC MEC			
SIZE	WEIGH PER FO			KIND OF SHOE	CUT AND PULLED FROM	PERFORATIONS	PURPOSE
	PER FO	OT USE		KIND OF		PERFORATIONS	PURPOSE
	PER F0	OT USE		KIND OF		PERFORATIONS	PURPOSE
size 10-3/4"	PER FO	OT USE		KIND OF		PERFORATIONS	Purpose  Burface  Production
	21.63	OT USE		KIND OF		PERFORATIONS	PURPOSE Surface
	21.63	OT USE	240.54 1226.76 3750.66	KIND OF	PULLED FROM	PERFORATIONS	PURPOSE
10-3/ <b>5"</b>	21.63	OT USE	240.54 1226.76 3750.66	Sales	PULLED FROM	PERFORATIONS  MUD  BRAVITY	PURPOSE  Production  AMOUNT OF MUD USED
10-3/4" F	PER FO	WHERE SET	MUDDING  NO. SACKS OF CEMENT	AND CEMENT	PULLED FROM  TING RECORD	MUD	Production  AMOUNT OF
10-3/4" F	21.63 23# 20#	OT USE	MUDDING  No. SACKS	Shoe Shoe Shoe Shoe Shoe Shoe Shoe Shoe	PULLED FROM  TING RECORD	MUD	Production  AMOUNT OF