

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-039-20448
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: SJ 29-5 Unit 009256
8. Well No. SJ 29-5 Unit #59
9. Pool name or Wildcat Basin DK - 71599

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	2. Name of Operator Phillips Petroleum Company 017654
3. Address of Operator 5525 Highway 64, NBU 3004, Farmington, NM 87401	4. Well Location Unit Letter <u>H</u> : <u>1590'</u> feet from the <u>North</u> line and <u>1100'</u> feet from the <u>West</u> line Section <u>31</u> Township <u>29N</u> Range <u>5W</u> NMPM County <u>Rio Arriba</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 6434' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Added MV to DK interval <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/2/02 MIRU Key #29. ND WH & NU BOP. PT-OK. COOH w/tubing. RIH w/CIBP & set @ 6000'. PT plug & casing to 550 psi - 45 min. OK. RU to frac. Ran GR/CCL/CBL - good cement across zones of interest. Ran GR/GSL. Perf'd MV @ 1 spf .34" holes - 5718', 5691', 5681', 5676', 5652', 5645', 5631', 5619', 5603', 5589', 5570', 5538', 5514', 5488', 5385', 5365', 5323', 5252', 5235', 5209', 5196 - 21 holes. Acidized perms w/1500 gal 15% HCL. RD & MO rig 4/6/02. 4/8/02 RU to frac. Pumped 78,674 gal of 56 Quality foamed Slickwater w/819,900 scf N2 & 75,040# 20/40 sand. Flowed back on 1/4" and 1/2" chokes. Set CIBP @ 5120'. Blue Jet perf'd Lewis Shale-1 spf .34" holes - 5062', 52', 20', 12', 08', 05', 4976', 4819', 4794', 4678', 4592', 72', 67', 60', 53', 42', 4469', 15', 02', 4395', = 20 holes. Acidized w/1000 gal 15% HCL. Frac'd w/79,398 gal of SFC 3000 foam consisting of 30# X-link gel & 886,200 scf N2 and w/201,960 # 20/40 proppant. Flowed back on 1/4" and 1/2" chokes. SI. 6/18/02 MIRU Key #29. ND WH & NU BOP. RIH w/bit & D/O CIBPs @ 5120' & 6000'. C/O to PBTD @ 7881'. COOH. RIH w/2-3/8", 4.7# tbg & set @ 7814' w/"F" nipple set @ 7806'. ND BOP. NU WH. Pumped off exp. check. RD & released rig 6/20/02. Turn over to Prod. Will DHC per Order 688AZ.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patsy Clugston TITLE Sr. Regulatory/Proration Clerk DATE 7/3/02

Type or print name Patsy Clugston Telephone No. 505-599-3454

(This space for State use)

APPROVED BY Original State Engineer JOHN HAYDEN TITLE DEPUTY OIL & GAS INSPECTOR DATE JUL - 5 2002
Conditions of approval, if any: