UNITED STATES SUBMIT IN TRIPLICATE (Other instructions on reverse side) Form approved. Budget Bureau No. 5. LEASE DESIGNATION AND SI

DATE ___

GEOLOGICAL SURVEY			SF 080596
	NOTICES AND REPORTS (proposals to drill or to deepen or plug b		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS [V]			7. UNIT AGREEMENT NAME
WE'L WELL X OT 2. NAME OF OPERATOR	HER	,	San Juan 29-6 Unit
Northwest Pipeline Corporation			San Juan 29-6 Unit
3. ADDRESS OF OPERATOR P.O.	Box 90 Farmington, New	Mexico 87401	9. WELL NO. #57A
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAY Blanco Mesa Verde
1090' FSL & 890' FEL			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
	•	\ \$\frac{\sqrt{\sq}\sqrt{\sq}}}}}}}}}\eqiintite\sintitita}\sign{\sign{\sqrt{\sqrt{\sq}}\sqrt{\sintitit{\sqrt{\sinq}\sqrt{\sqrt{\sqrt{\sqrt{\sq}}\sign{\sign{\sq}\sign{\sign}\eq}\sign{\sign{\sign{\sqrt{\sinq}}\eqs}\eqsi}\eqsi\tinititin}	Sec. 33, T29N, R6W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	, RA GR, etc.	12. COUNTY OR PARISH 13. STATE
	6484' GR		Rio Arriba N.M.
16. Chec	ck Appropriate Box To Indicate N	lature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO:			ENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT SHOOT OR ACIDIZE	MULTIPLE COMPLETE ABANDON*	FRACTURE TREATMENT X SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT
REPAIR WELL	CHANGE PLANS	SECOLUM ON HOLDING	Completion"
(Other)		(Note: Report results Completion or Recompl	of multiple completion on Well etion Report and Log form.)
9-7-75 9-8-75 9-11-75	Drilled 8 3/4" hole to 7", 20#, K-55 casing, s Howco cemented w/150 sk @ 2530' by temp. survey held OK. Drilled 6 1/4" hole to Density logs. Ran 72 j casing liner, set @ 576	et @ 3681' KB with se s. cement. WOC 12 ho . Tested casing to 7 5766' w/gas. Welex r oints (2285') 4 1/2", 6' KB. Top of liner	even centralizers. Fours. Top of cement On psi for 1/2 hr., Fran Gamma Ray and 10.5#, K-55 © 3480', F.C.
9-12-75	@ 5732'. Howco cemented 2/215 sks. of cement. WOC 18 hours. Cleaned out to F.C. @ 5732'. Tested liner to 3500 psi; held OK. Spotted 500 gal. 7 1/2% HCl. Ran GR/CCL log and perforated w/29 shots from 5130' to 5720'. Pumped 1000 gal. 7 1/2 HCl w/40 ball sealers. Dowell frac'd w/80,000 lbs. 20/40 sand and 90,000 gal. of treated water.		
9-14-75	Ran 181 joints (5684') KB. Kicked well off th		
SIGNED D.H. Maro	/1//	troleum Engineer	Sept. 15, 1975
(This space for Federal or Sta	ate office use)		

TITLE

APPROVED BY ______CONDITIONS OF APPROVAL, IF ANY: