Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

SF-078426-A

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FO	R PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well		San Juan 29-6 Unit
Oil Sas Other		8. Well Name and No.
2. Name of Operator		SJ 29-6 Unit #73A
Phillips Petroleum Company	y 505-599-3454	9. API Well No.
3. Address and Telephone No.		30-039-21249
5525 Hwy. 64, NBU 3004, Fa	armington, NM 84701	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey De		Blanco Mesaverde
Unit D, 820' FNL & 820' FV	NL	11. County or Parish, State
Section 20, T-29-N, R-6-W		
· · · · · · · · · · · · · · · · · · ·		Rio Arriba, NM
2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other <u>perforate & prodi</u>	Dispose Water
	Lewis Shale	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
	pertinent details, and give pertinent dates, including estimated date of starting all depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled,
& casing. RUN GR/CCL & CN @ 1 spf w/120 degree phas:	ug above current Mesaverde perforate the Lewing. Frac the Lewis Shale. Retubing w/gas lift mandrel and bla	vis Shale formation crieve bridge plug.

Set retrievable bridge plug above current Mesaverde perfs. Pressure test RBP & casing. RUN GR/CCL & CNL if needed. Perforate the Lewis Shale formation @ 1 spf w/120 degree phasing. Frac the Lewis Shale. Retrieve bridge plug. RIH w/2-3/8" production tubing w/gas lift mandrel and blast joints across Lewis perfs, 4-1/2" production packer and "R" profile nipple above the bottom joint of tubing and an expendable check valve on the end of the tubing. Using a slick line, remove blanking plug. Produce Lewis for a period of time to record daily volumes and pressures and then produce both zones.

MAN 13 Old Carlotte English 3-4-96

	Section 1987 (1984) - 1995	
4. I hereby certify that the foregoing is true and correct	Survey of the proper to the form of the control of	
Signed Ed Hasely	Title Environmental/Regulatory Eng ate_	3-4-96
(This space for Federal or State office use)	APPI	ROVED
Approved by	Title Date	

MAR 0 7 1996

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.