Form 3160-5

# **UNITED STATES**

FORM APPROVED				
Budget Bureau No.	1004-0135			
D ' 14 10	1 1002			

June 1990)	DEPARTMENT OF THE INTERIOR				Expires: March 31, 1993
ine 1999)	BUREAU OF LAND	MANAGEM	ENT	5.	Lease Designation and Serial No.
24	INDEX MOTIONS AND DE	TOOTO ON	MELLS	NM -	012698
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.					If Indian, Allottee or Tribe Name
Use_	"APPLICATION FOR PERM	IIT - " for suc	h proposals	<del>-</del>	If Unit or CA, Agreement Designation
· · · · · · · · · · · · · · · · · · ·	SUBMIT IN 1	TRIPLICATE	pecely	国则	Juan 29-6 Unit
I. Type of Well Oil X Gas Well Well	Other		UU AUG 1 7 199	<b>38</b>	Well Name and No.
2. Name of Operator Phillips Petroleul	m Company		ത്വെ രണ പ		29-6 Unit #17A
3. Address and Telephone No.	ii computiy		COMP FI	,,,,,,,	API Well No. 039-21415
-	NBU 3004, Farmington,	NM 87401	505-599-3454 <b>DIST. 3</b>		Field and Pool, or exploratory Area
	ec., T., R., M., or Survey Descriptio	n)			
Unit J, 1470' FSL		nco Mesaverde County or Parish, State			
Section 1, T29N,	R6W				•
		<del></del>			
12. CHECK APF	PROPRIATE BOX(s) TO	INDICATE I	NATURE OF NOTICE, REPO	RT, OR C	OTHER DATA
TYPE OF SUBM	MISSION		TYPE OF ACTION	<u>ON</u>	
Notice of In	tent		Abandonment	Ļ	Change of Plans
			Recompletion		New Construction
X Subsequent	Report		Plugging Back	Ļ	Non-Routine Fracturing
<del></del> 1			Casing Repair	L	Water Shut-Off
Final Aband	onment Notice		Altering Casing	Ļ	Conversion to Injection
		X	Other Add pay & stimulat	teL_	Dispose Water Note: Report results of multiple completion on Well
See attached for t Mesaverde formatio	the procedure used to a	add pay and	stimulate the Lewis Shale	interv	al in the existing
14. I hereby certify that the fore Signed  (This space for Federal or St. Approved by Conditions of approval, if as	ate office use)	Title	Regulatory Assistant		PAUG 1 4 1998
	·				
Title 18 U.S.C. Section 1001, nor representations as to any mat	nakes it a crime for any person knowi ter within its jurisdiction.	ngly and willfully to	o make to any department or agency of the	United States	s any false, fictitions of fraudulent statemen

\* See Instruction on Reverse Side

KIRADOD

### San Juan 29-6 Unit #17A NM-012698; Unit J, 1470' FSL & 885' FEL Section 1, T29N, R6W; Rio Arriba County, NM

## Procedure used to perf & stimulate the Lewis Shale interval in the existing Mesaverde formation.

#### 7/23/98

MIRU Big A #40. Killed well. ND WH & NU BOPs. Cleaned out fill from 5720' to 5740' (PBTD). COOH w/2-3/8" tubing. RIH w/4 ½" CIBP & set @ 5200'. Pressure test CIBP, casing & rams to 500 psi – 30 min. Held OK. RIH to log well. TOC 1070'. RIH & perf'd Lewis Shale interval @ 1 spf (.38" holes) 120 degree phased holes as follows: (Huerfanito Bentonite not present, equivalent stratigraphic depth is 3780').

4711' – 4714' (3');	4674' – 4677' (3');	4656' – 4659' (3');	4637' – 4640' (3');
4616' – 4619' (3');	4595' – 4598' (3');	4529' – 4532' (3');	4487' – 4490' (3');
4470' - 4473' (3');	4463' – 4466' (3');	4456' – 4459' (3');	4234' – 4237' (3'); <b>36 Holes Total</b>

GIH w/4 ½" packer & set @ 4006'. PT casing annulus & packer to 500 psi – OK. RU to Acidize Lewis Shale interval. Pumped 1000 gal of 15% HCL acid & ballsealers. Knocked balls off & COOH w/packer.

RIH & set 4  $\frac{1}{2}$ " packer @ 3601'. PT casing annulus to 500 psi -OK. RU to frac Lewis Shale. Pumped 21,756 GAL 60 Quality N2 30# X-link Borate foam with 86,000 # 20/40 Brady sand. Total N2 – 566,000 scf, total fluid to recover 425 bbls. AVT 2600 psi and ATR – 45 bpm. ISIP 638 psi. Flowed back on 2  $\frac{1}{4}$ " choke for approximately 34 hrs.

Released packer and COOH. RIH & cleaned out to CIBP @ 5200'. Chased CIBP to (PBTD). RIH w/2-3/8" 4.7= tubing and cleaned out to new PBTD (5736' – has 4' fill). Land tubing @ 5689' with "F" nipple set @ 5655'. ND BOPs & NU WH. Pumped off exp. check. RD & released rig 7/29/98. Turned well over to production department.