

San Juan 29-5 Unit #209

H-29-29N-05W

PHILLIPS PETROLEUM CO.

---

F

30-039-24678

04-02-90

F. Loc. 1445/N; 1205/E Elev. 6743 GL Spd. \_\_\_\_\_ Cu. ft. \_\_\_\_\_ Cu. ft. \_\_\_\_\_ Cu. ft. \_\_\_\_\_  
 Casing S. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Int. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Pr. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. T. \_\_\_\_\_ @ \_\_\_\_\_  
 Csg. Perf. \_\_\_\_\_ Prod. Stim. \_\_\_\_\_

T Gas  
R  
A  
N  
S

BO/D \_\_\_\_\_ Grav. \_\_\_\_\_ 1st Del. Gas \_\_\_\_\_  
 I.P. \_\_\_\_\_ MCF/D After \_\_\_\_\_ Hrs. SICP \_\_\_\_\_ PSI After \_\_\_\_\_ Days GOR \_\_\_\_\_ 1st Del. Oil \_\_\_\_\_

| TOPS            |  | NITD  | Well Log     | TEST DATA |    |   |    |    |   |         |
|-----------------|--|-------|--------------|-----------|----|---|----|----|---|---------|
|                 |  |       |              | Schd.     | PC | Q | PW | PD | D | Ref.No. |
| Ojo Alamo       |  | C-103 | Plot X       |           |    |   |    |    |   |         |
| Kirtland        |  | C-104 | Electric Log |           |    |   |    |    |   |         |
| Fruitland       |  |       | C-122        |           |    |   |    |    |   |         |
| Pictured Cliffs |  | Ditr  | Dfa          |           |    |   |    |    |   |         |
| Chacra          |  | Datr  | Dac          |           |    |   |    |    |   |         |
| Cliff House     |  |       |              |           |    |   |    |    |   |         |
| Menefee         |  |       |              |           |    |   |    |    |   |         |
| Point Lookout   |  |       |              |           |    |   |    |    |   |         |
| Mancos          |  |       |              |           |    |   |    |    |   |         |
| Gallup          |  |       |              |           |    |   |    |    |   |         |
| Greenhorn       |  |       |              |           |    |   |    |    |   |         |
| Dakota          |  |       |              |           |    |   |    |    |   |         |
| Entrada         |  |       |              |           |    |   |    |    |   |         |
| Acres E/320     |  |       |              |           |    |   |    |    |   |         |

P  
o  
o

BasinFrCoal Co. RA S 29 T 29N R 05W UH Oper. Phillips Petroleum Co. Lse. San Juan 29-5 Unit No. 209



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA  
1235 LAPLATA HIGHWAY  
FARMINGTON, NEW MEXICO 87401

TAKE  
PRIDE IN  
AMERICA

IN REPLY REFER TO:

SF-078282 et al. (WC)  
3162.3-1(F) (019)

JUN. 20 1991

**RECEIVED**

JUN 21 1991

**OIL CON. DIV.**  
**DIST. 3**

Phillips Petroleum Company  
5525 Highway 64, NBU 3004  
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) well Nos.:

1. No. 204 ✓ San Juan 29-5 Unit, NW/4NE/4, sec. 19, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078282.
2. No. 205 ✓ San Juan 29-5 Unit, NW/4NE/4, sec. 20, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078281.
3. No. 208 ✓ San Juan 29-5 Unit, SW/4SW/4, sec. 21, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, NM-03188.
4. No. 209 ✓ San Juan 29-5 Unit, SE/4NE/4, sec. 29, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078282.
5. No. 210 ✓ San Juan 29-5 Unit, SE/4SW/4, sec. 29, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078282.
6. No. 211 ✓ San Juan 29-5 Unit, SE/4NE/4, sec. 30, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-079851.
7. No. 212 ✓ San Juan 29-5 Unit, SE/4SW/4, sec. 30, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-079851.
8. No. 205 ✓ San Juan 32-7 Unit, SE/4SW/4, sec. 22, T. 32 N., R. 7 W., San Juan County, New Mexico, SF-078459.
9. No. 206 ✓ San Juan 32-7 Unit, SW/4NE/4, sec. 27, T. 32 N., R. 7 W., San Juan County, New Mexico, SF-078472.

As discussed with Gail Bearden of your company on June 10, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 30 days, we will presume that no

**ABANDONED LOCATION**

construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ Duane Spencer

FOR John L. Keller  
Chief, Branch of Mineral Resources

9 Enclosures

cc: ~~.....~~  
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410