

UNITED STATES  
DEPARTMENT OF INTERIOR  
BUREAU OF LAND MANAGEMENT

5. Lease Description and Serial No.

NM - 18319 18318

SUDRY NOTICES AND REPORTS ON WELLS

(Do Not use this form for proposedals to drill or to deepen or plug back to a different resevoir. Use Form 3160-3 for such proposals)

6. If Indian, Allottee or tribe Name

7. If Unit or CA, Agreement Number

1. Type of Well

GAS WELL

8. Well Name and No.

29-4 CARSON 19 # 1

2. Name of Operator

FALCON SEABOARD OIL COMPANY

9. API Number

30-039-24991

3. Address and Telephone Number

C/O DAVE SIMMONS P. O. BOX 48 FARMINGTON, NM 87499

10. Field and Pool, or Exploratory Acres

Basin Fruitland Coal Gas Pool

4. Location of Well (Sec., T., R., or Survey Description)

1910' FNL & 655' FEL  
Sec. 19, T29N, R4W

11. County or Parish

Rio Arriba Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE THE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
- ☒ Subsequent Report
- ☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
- ☒ Recompletion
- ☐ Plug Back
- ☐ Casing Repair
- ☐ Alter Casing
- ☐ Other:
- ☐ Cahnge of Plans
- ☐ New Construction
- ☐ Non-Routine Fracturing
- ☐ Water Shut-Off
- ☐ Conversion to Injection
- ☐ Disposal Water
- (Note Report result of multiple completions on Well  
Completion or Recompletion Report and Log Form)

13. Describe Proposed Completion Operations (Clearly state all pertinent details, and give pertinent dates, including estimated starting and proposed work. If well is directionally drilled give subsurface location and measured and true vertical depths for all markers and zones pertinent to this work.)\*

OPERATOR TA'D FRUITLAND COAL AS FOLLOWS:

- Set cast iron bridge plug above Fruitland Coal formation inside 7" casing @3050 (Fruitland cavitated'). Pressure test to 2000 psig.
- Ran GAS SPECTRUM/corelation log from 3000-1500'.  
Selectively Perforated Nacimiento as follows:  
1674,1736,2030,2035,2040,2123,2156,2165,2172,2291,2390,2398,2455,2472,2476
- Acidized perforations with 1500 gals 15% HCL.
- Swab tested Nacimiento formation water and gas. Shut well in due to Forest Service Requirements.
- Plan to evaluate workover and continue workover in spring of 1996.

RECEIVED  
APR 25 1996

NOTE: This format is issued in lieu of U.S. BLM Form 3160-5

OIL CON. DIV.  
DIST. 3

14. I hereby certify that the foregoing is true and correct

SIGNED

R. D. SIMMONS

TITLE

AGENT

DATE:

12/07/95

(This space for Federal or Stae Office use.)

APPROVED BY:

TITLE

DATE:

CONDITIONS OF APPROVAL, IF ANY

ACCEPTED FOR RECORD

DEC 14 1995

FARMINGTON DISTRICT OFFICE  
BY 215

NMOCD