UNITED STATES DEPARTMENT OF THE INTERIOR RECEIVED



Sundry Notices and Reports on Wells	PH 1: 19	,32
1. Type of Well GAS DECEIN 2. Name of Operator O70 FARM DECEIN	MOTON, MM5.	Lease Number SF-078945 If Indian, All. or Tribe Name Unit Agreement Name San Juan 29-7 Unit
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 1725' FSL, 2205' FWL, Sec. 28, T-29-N, R-7-W, NMPM	9.	Well Name & Number San Juan 29-7 U #41C API Well No. 30-039-25913 Field and Pool Blanco Mesaverde County and State Rio Arriba Co, NM
Recompletion X_ Subsequent Report Plugging Back	on Change of Pl New Construc Non-Routine Water Shut o Conversion t	ans tion Fracturing ff
13. Describe Proposed or Completed Operations 8-11-98 Drill to TD @ 5893'. Circ hole clean. J-55 lnr, set @ 5893'. Lnr top @ 3373' 50/50 poz w/2% gel, 0.25 pps Flocele, 9 loss (396 cu ft). Circ 5 bbls cmt to s RD. Rig released.	'. Cmtd w/300 5 pps Gilsonit	O sx Class "B" ce, 0.4% fluid
14. I hereby certify that the foregoing is true and co Signed Sidned Title Regulatory Admi (This space for Federal or State Office use)		e 8/20/98 vkh ccepted for hecori
APPROVED BYTitle CONDITION OF APPROVAL, if any:	Date	AUG 81 1998
-		MOR OF WALL