Form 9-331 (May 1963)

D

		Rudget	Burea	u I	Nο.	/42	R142
ī.	LEASE	DESIGN	ATION	ANI) /	ERIA	L NO

(MILLED SIAIES	(Other instructions on re-
DEPARTMENT OF THE INTERIOR	verse side)
GEOLOGICAL SURVEY	

GEOLOGICAL SURVEY	SF 078502A			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
I.	7. UNIT AGREEMENT NAME			
OIL GAS WELL X OTHER	S. FARM OR LEASE NAME			
2. NAME OF OPERATOR	Hardie A			
El Paso Natural Gas Company 3. Address of Operator	9. WELL NO.			
Box 990, Farmington, New Mexico 87401 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	2A 10. FIELD AND POOL, OR WILDCAT			
4. Location of Well (Report location Clearly and in accordance with any beast required See also space 17 below.) At surface	Blanco Mesa Verde			
800'N, 1700'W	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA			
800 N, 1700 N	Sec. 24, T-29-N, R-8-W			
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	N.M.P.M. 12. COUNTY OR PARISH 13. STATE New Movi co			
6706' GL	San Juan New Mexico			
16. Check Appropriate Box To Indicate Nature of Notice, Report,	or Other Data			
	BSEQUENT REPORT OF:			
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	X REPAIRING WELL			
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	X ALTERING CASING ABANDONMENT*			
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING CHANGE PLANS (Other)				
(Note: Report re	esults of multiple completion on Well completion Report and Log form.)			
(Other) 17. DESCRIBE PROPOSED OR COMPLETED OFERATIONS (Clearly state all pertinent details, and give pertinent of proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.) *	dates, including estimated date of starring and cortical depths for all markers and zones perti-			
09-09-76 T.D. 3704'. Ran 91 joints 7", 20#, KS intermediation of the state of the s	2 hours, herd 12007/30			
09-13-76 T.D. 5968'. Ran 75 joints 4 1/2", 10.5#, K-55 c 3585-5968'. Float collar set at 5952'. Cemente WOC 18 hours.	ed With 421 ca. it. coment			
10-16-76 PBTD 5952'. Tested casing to 3500, OK. Perfed 5125', 5139', 5155', 5168', 5175', 5185', 5283', 5438', 5455' with 1 shot per zone. Fraced with 56,200 gallons water. No ball sets dropped. Fl Perfed 5581', 5586', 5593', 5600', 5607', 5612', 5676', 5702', 5718', 5774', 5836', 5871', 5897', Fraced with 65,000#20/40 sand and 66,600 gallod dropped. Flushed with 7740 gallons water.	50,000#20/40 sand and ushed with 7360 gallons water, 5619', 5640', 5654', 5662', 5937' with 1 shot per zone.			
	I alm Count V Land			
,	OCT 1 0 1 976			
18. I hereby certify that the foregoing is true and correct	1076			
SIGNED Jucico TITLE Drilling Clerk				
(This space for Federal or State office use)				
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE			

*See Instructions on Reverse Side

001 S 0 1976 Cir Con. COM, DIST. 3