30-045-25263 15 20/5 815/W F. Loc 1725/S; 800/W 12-3-81 ___Elev. 6382 GL Spd.____ ______TD______PB___ __Sx. Int.____ _____Sx. Pr.___ ___w__ Csg.Perf. Prod. Stim. BO/D MCF/D After_ Hrs. SICP_ _PSI After_____Days GOR_ _i st Dei. TOPS NITD Well Log TEST DATA Kirtland C-103 Plat Schd. PC Q PW D Ref.No. Fruitland C-104 Electric Log Pictured Cliffs C-122 Cliff House Ditr Dfa Menefee Datr NSL applied for 16-81 Point Lookout Mancos Gallup Sanostee Greenhorn Dakota Morrison Entrada

Blanco PC Co. SJ S 6 7 29N R8W UL Oper Union Texas Pet. Corp. Lac. Prichard Federal No. 4

NWU-R3669

Prichard Federal #4

L-6-29N-8W

Union Texas Petroleum Corp.

•	. F			30-045-25263				12-3-81				
/52/ F. Loc. 172		Elev. 63	82 GL_Spd		Comp		1D		PE	3		
	@w	Sx. Int		w	Sx. Pr Prod. Stim.			v	Sx. T		@	T R
I.P	BO/D _MCF/D After	Hrs. SICP_	PSI	After	Days GOR	G	rov		l st Del		s	N 5
TOPS		NITD X		Well Log		TEST DATA						
Kirtland		C-103		Plat y	ζ	Schd.	PC	Q	PW	PD	D	Ref.No.
Fruitland		C-104		Electric Log								
Pictured Cliffs				C-122					[
Cliff House		Ditr	<u> </u>	Dfa								<u> </u>
Menefee		Datr		Dac						<u> </u>		
Point Lookout				A Si upplied	fr. 11-16-81				<u> </u>	ļ	<u> </u>	
Mancos		1								ļ	<u> </u>	<u> </u>
Gallup			Se. 1	2 Z	-				<u> </u>	ļ	 	_
Sanostee										ļ	↓	
Greenhorn									<u> </u>	<u> </u>	 	ļ
Dakota									<u> </u>	↓	 	
Morrison						<u></u>				_	↓	
Entrada										<u> </u>	↓	
		1			182.95	1		l		1	<u> </u>	

P

O

O

Basin Dakota O

SJ S 6 7 29N R 8W UL Oper. Union Texas Pet. Corp. Lee. Prichard Federal No. 4

Drawer 600 Farmington, New Mexico 87499

JUN 2 9 1983

CERTIFIED

Union Texas Petroleum Corporation P. O. Box 808 Farmington, New Mexico 87499

Gentlemen:

Reference is made to your Application for Permit to Drill (APD) well No. 4 Prichard Federal, NV\\$SW\\$ sec. 6, T. 29 N., R. 8 W., San Juan County, New Mexico, lease Santa Fe 078487-B. As discussed with Mr. W. K. Cooper of your Company on June 21, 1983, the subject APD is hereby rescinded and returned due to drilling operations not being commenced within a six month extension period following the original approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in assessment of liquidated damages.

Sincerely yours,

For Acting Area Manager

Enclosure

cc: NMOCC /

REGEIVED

OIL CON. DIV.