## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

5. Lease Designation and Serial No.

runi	VI AFFN	OVE	ט
udget Bur	eau No.	100	04-0135
Expires:	March	31,	1993

	TICES AND REPORTS ON Woosals to drill or to deepen or reentry to a d	/	SF-078	31,32
Use "APPLICA	ATION FOR PERMIT - " for such proposa	s		
			7. If Unit or CA, Agreement De	esignation
1. Type of Well Oil Well Gas Well Other			8. Well Name and No.	
2. Name of Operator	Attention:		A. L. Elliott A	3
Amoco Production Company	Lois Raeb	urn	9. API Well No.	
3. Address and Telephone No.		03) 830-5294	30045-2	
P.O. Box 800, Denver, Colorado	3 80201		Blanco Pictu	
4. Location of Well (Footage, Sec., T., R., M., or	Survey Description)		11. County or Parish, State	
1165FNL 1120FEL	Sec. 11 T 29N R 09	<b>W</b>	San Juan	New Mexico
12. CHECK APPROPRI	ATE BOX(s) TO INDICATE NA	TURE OF NOTICE, R	EPORT, OR OTHER	DATA
TYPE OF SUBMISSION		TYPE OF ACTION		·
Notice of Intent  Subsequent Report  Final Abandonment Notice  13. Describe Proposed or Completed Operations (	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other  Clearly state all pertinent details, and give pertinent dates	Recompletio	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water rt results of multiple completion or Report and Log form.) any proposed work . If well is di	
	vertical depths for all markers and zones pertinent to this request permission to Plug and Abanc		well.	
Amoco Froduction Company	request permission to ring and mount			
See attached procedures.  If you have any questions con	ntact Lois Raeburn, @(303)830-5	294		8 20 MIP 19 10 MIP 19 MIP 19 10 MIP
		DIEGETS JUN 3 0 19 ONL GOM. E DIST. 3	Men 2 :	2 (n)
		· · · · · · · · · · · · · · · · · · ·		
14. I hereby certify that the foregoine is true and Signed Signed	correct Title	Business Ass	ociate Date	06-13-1994
(This space for Federal or State office use)				
			APPROVE	D
Approved by  Conditions of approval, if any:	Title		APPROVE AS AMEND	ĒD
Title 18 U.S.C. Section 1001, makes it a crime for representations as to any matter within its jurisdictions.	or any person knowingly and willfully to make to any dep ction.	artment or agency of the United State	es any false	nd statements or

P&A A L Elliott A 3 - PC Run 35 June 8, 1994

## Procedure:

- 1. Move in rig. Rig Up. Nipple up blowout preventer.
- 2. Kill well. Pull tubing.
- 3. Run work string and spot cement across PC zone to at least 2796'(150' above the top of the PC perfs). Pull tubing up out of cement. Apply 500 psi pressure to the cement column to obtain a squeeze. Allow the cement to set for 24 hours.
- 4. Pressure test cement to 1000 psi. Run in with tubing and tag cement top to be sure cement is 150' above the top perf. Set new cement if necessary.
- 5. Fill hole with plugging fluid.
- Test Bradenhead for pressure. Contact Stan Kolodzie if Bradenhead flows gas or water.
   Last available test showed no leakage. If bradenhead leaks, further squeezing will be required.
- 7. Set surface plug 100 feet of cement. Allow cement to set for 24 hours. Pressure test plug to 1000 psi.
- 8. Set P&A marker.
- 9. Remediate or rehabilitate surface location in accordance with federal regulations.

AUTHORIZATIONS	
ENGINEER	Marley Kolodie
PRODUCTION FOREMAN	8 0 /
WORKOVER FOREMAN	

EABLE 400 0 ...