## UNITED STATES

SUBMIT IN TRIPLICATE\*

Form approved. Budget Burgau No. 42-R1424.

5.	LEASE	DESIG	NATIO	AND	SERIA

G	GEOLOGICAL SURVEY			
SUNDRY NOTIC (Do not use this form for proposa Use "APPLICAT	ok to a different reservoir.	7. UNIT AGREEMENT NAME		
OIL GAS WELL OTHER  2. NAME OF OPERATOR  LONE STAR INDUSTRIES 3. ADDRESS OF OPERATOR  P.O. Box 2078, FARMI 4. LOCATION OF WELL (Report location cleans and surface) At surface  790' FROM THE NORTH SECTION 12, TOWNSHIE	LINE, 1615' FROM 2 30 NORTH, RANGE	State requirements.*  THE WEST LINE 5 WEST	8. FARM OB LEASE NAME  SCHALK - 57  9. WELL NO.  1  10. FIELD AND POOL, OR WILDCAT  BASIN DAKOTA  11. SEC., T., R., M., OR BLK. AND  SURVEY OR AREA  SEC. 12, T-30-N, R-5-  12. COUNTY OR PARISH 13. STATE	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF. 6581.0 *		RIO ARRIBA NEW MEXICO	
MOTICE OF INTEN	FRACTURE TREAT MULTIPLE COMPLETE		REPAIRING WELL.  ALTERING CASING  ABANDONMENT*	
REPAIR WELL	CHANGE PLANS  CRATIONS (Clearly state all pertine) on ally drilled, give subsurface local	Completion or Recomp	of multiple completion on Well letion Report and Log form.) , including estimated date of starting any al depths for all markers and zones perti-	

NO. 2 - CHANGE DESIGNATION OF OPERATOR:

LONE STAR INDUSTRIES, INC. FROM:

C/O JOHN E. SCHALK

P. O. BOX 2078

FARMINGTON, NEW MEXICO 87401


TO:

COASTLINE PETROLEUM COMPANY, INC.

c/o JOHN E. SCHALK

P. O. BOX 2078

FARMINGTON, NEW MEXICO 87401



DATE Sept. for Federal or State office use) DATE APPROVED BY CONDITIONS OF APPROVAL, IF ANY: