

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 4455

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
LONE STAR INDUSTRIES, INC.	SCHALK 55
3. ADDRESS OF OPERATOR	9. WELL NO.
% JOHN E. SCHALK	2
P. O. BOX 2078, FARMINGTON, NEW MEXICO 87401	10. FIELD AND POOL, OR WILDCAT
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also Space 17 below.) At surface	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
980' FROM THE NORTH LINE, 1180' FROM THE EAST LINE	SEC. 3, T-30N, R-5W
14. PERMIT NO.	12. COUNTY OR PARISH
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	13. STATE
6486' GR	RIO ARRIBA NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRAC TURE TREAT

MULTIPLE COMPLETE

FRAC TURE TREATMENT

ALTERING CASING

SHOOT & SIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

WELL HISTORY

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SCHALK 55 WELL NO. 2

SPUDDED AT 11:00 PM ON 8-7-74

8-24-74

TOTAL DEPTH 5975'

RAN 181 JOINTS OF 4-1/2" 10.50# CASING (62 JOINTS OF K55 + 119 JOINTS OF H-40) TOTALING 5990'. SET AT 5975'. D.V. TOOL SET AT 1986' AND 3991'. FLOAT SET AT 5942'. CEMENTED FIRST STAGE WITH 160 SACKS 50/50 POSMIX WITH 12-1/2# GILSONITE PER SACK AND 125 SACKS OF HALLIBURTON LIGHTWEIGHT WITH 12% GEL AND 12-1/2# GILSONITE AND 1/4# FLOEAL PER SACK. CEMENTED SECOND STAGE WITH 275 SACKS HALLIBURTON LIGHTWEIGHT WITH 12% GEL, 12-1/2# GILSONITE, AND 1/4 FLOEAL PER SACK. CEMENTED THIRD STAGE WITH 265 SACKS OF HALLIBURTON LIGHTWEIGHT WITH 12% GEL, 12-1/4# GILSONITE, AND 1/4# FLOEAL PER SACK. PLUG DOWN AT 10:25 AM. CIRCULATED WITH GOOD RETURNS.

18. I hereby certify that the foregoing is true and correct

SIGNED

John E. Schalk

TITLE

AGENT

DATE 8-28-74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: