UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED BLM

Sundry Notices and Reports on St	23 PH 1:33	
	ARMINGTON, NM 6	. Lease Number NM-02151 . If Indian, All. or Tribe Name
	7	. Unit Agreement Name
2. Name of Operator		
MERIDIAN OIL	Q	San Juan 30-6 Unit . Well Name & Number
3. Address & Phone No. of Operator	_	San Juan 30-6 U #912
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9	. API Well No. 30-039-22193
4. Location of Well, Footage, Sec., T, R, M	_ 1	0. Field and Pool
835'FSL, 580'FEL, Sec.28, T-30-N, R-7-W, NMPM	1	Blanco Mesaverde 1. County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTIC	E, REPORT, OTH	ER DATA
Type of Submission X Notice of Intent Becompletion Subsequent Report Final Abandonment X Other - Type of A Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other -	Change of New Constr Non-Routin Water Shut	uction e Fracturing off
13. Describe Proposed or Completed Operations		
Meridian Oil Inc. moved on location to check for It is intended to squeeze at 1659-2034' "B" cement. Wait on cement. Drill out a squeeze from Wayne Townsend, BLM).	with approxima	ately 100 sacks Class
		ing real
	LIVE SEP 2	
	ON CO	M. DIV. I. s
14. I hereby certify that the foregoing is true and	l correct.	
Signed Signed (ROS7) Title Regulat		tor Date 9/16/96
(This space for Federal or State Office use) APPROVED BY Title	Date4	PPROVED
CONDITION OF APPROVAL, if any:		SEP 2 4 1996

DISTRICT MANAGER