



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

BRUCE KING
GOVERNOR

LARRY KEHOE
SECRETARY

July 20, 1981

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

El Pamco Inc.
P.O. Box 14738
Albuquerque, New Mexico 87108

Re: Lechner #1 F-30-29N-10W

Gentlemen:

A recent field inspection of the referenced well discovered gas being produced with the water flowing from the casing of this well. Vegetation to the west of this well has been killed or stunted also indicating a casing failure. The recent bradenhead test on this well was incomplete as only one casing string was tested.

You are hereby directed to retest the bradenhead of this well and locate and repair the casing failure. Notify this office prior to testing so that we may provide a witness.

If you have any questions, please contact this office.

Yours truly,

Frank T. Chavez
District Supervisor

XC: Santa Fe
Reading File

al