

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Aztec Oil & Gas Company	8. Farm or Lease Name Aztec Totah Unit
3. Address of Operator P. O. Drawer 570, Farmington, New Mexico	9. Well No. #17
4. Location of Well UNIT LETTER E, 2080 FEET FROM THE North LINE AND 810 FEET FROM THE West LINE, SECTION 20 TOWNSHIP 29N RANGE 13W NMPM.	10. Field and Pool, or Wildcat Totah Gallup
15. Elevation (Show whether DF, RT, GR, etc.) 5378' GR	12. County San Juan


Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROPOSE TO:

- (1) Pull 2-3/8" Tubing.
- (2) Squeeze Perforations From 5190' To 5208'.
- (3) Spot Plug From 100' Below Pictured Cliff To 100' Above Pictured Cliff.
- (4) Spot 10 Sack Plug At Surface.
- (5) Install Dry Hole Marker.
- (6) Well Has Two Stages, DV Collar At 1330', Cemented With 150 Sacks.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE District Superintendent DATE November 1, 1973
APPROVED BY [Signature] TITLE SUPERVISOR DIST. #3 DATE NOV 5 1973
CONDITIONS OF APPROVAL, IF ANY: