Spotted a 60 sack plug across Dakota from 5650'. Shot 4 holes at 1000'. Squeezed with 40 sacks cement. Shot holes at 196'. Spotted a 50 sack plug. Installed dry hole marker.	7-78
Shot 4 holes at 1000'. Squeezed with 40 sacks cement. Shot holes at 196'. Spotted a 50 sack plug. Installed dry hole marker.	7-78
Shot 4 holes at 1000'. Squeezed with 40 sacks cement. Shot holes at 196'. Spotted a 50 sack plug. Installed dry hole marker.	
Shot 4 holes at 1000'. Squeezed with 40 sacks cement. Shot holes at 196'. Spotted a 50 sack plug.	
Shot 4 holes at 1000'. Squeezed with 40 sacks cement.	
Spotted a 60 sack plug across Dakota from 5650'.	
Pulled rods and tubing.	
11-1-77 thru 11-4-77	
Work performed	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includit work) SEE RULE 1103.	ag estimated date of starting any proposed
OTHER	
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALYERING CASING
Check Appropriate Box To Indicate Nature of Notice, Report of ONDICE OF INTENTION TO:	other Data NT REPORT OF:
5252' GR	San Juan
THE West LINE, SECTION 21 TOWNSHIP 29N RANGE 13W NMF	M. 12. County
UNIT LETTER E . 1750 FEET FROM THE NOTTH LINE AND 890 FEET FR	Basin Dakota
P. O. Drawer 570, Farmington, New Mexico 87401	#1 10. Field and Pool, or Wildcat
Aztec Oil & Gas Company 3. Address of Operator	Gerard "A" 9. Well No.
2. Name of Operator	8. Farm or Lease Name
1. OIL GAS WELL X OTHER-	7. Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OPERATOR 2	5. State Oil & Gas Lease No.
U.S.G.S.	Sa, Indicate Type of Lease State Fee X
	Effective 1-1-65
SANTA FE I NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103