

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

**RECEIVED
BLM**

Sundry Notices and Reports **96 JUL 25 PM 3:19**

1. Type of Well
GAS

RECEIVED
JUL 30 1996

070 FARMINGTON, NM

5. Lease Number
SF-078716A
6. If Indian, All. or
Tribe Name
7. Unit Agreement Name
8. Well Name & Number
San Jacinto #6
9. API Well No.
30-045-08130
10. Field and Pool
Basin Dakota
11. County and State
San Juan Co, NM

2. Name of Operator
MERIDIAN OIL

**OIL CON. DIV.
DIST. 3**

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
840' FNL, 890' FWL, Sec. 20, T-29-N, R-10-W, NMPM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

- | | | |
|---|---|--|
| ☐ Notice of Intent | ☒ Abandonment | ☐ Change of Plans |
| ☒ Subsequent Report | ☐ Recompletion | ☐ New Construction |
| ☐ Final Abandonment | ☐ Plugging Back | ☐ Non-Routine Fracturing |
| | ☐ Casing Repair | ☐ Water Shut off |
| | ☐ Altering Casing | ☐ Conversion to Injection |
| | ☐ Other - | |

13. Describe Proposed or Completed Operations

- 7-15-96 MIRU. ND WH. NU BOP. TOO H w/206 jts 2 3/8" tbq. TIH w/4 1/2" cmt retainer, set @ 6259'. TOO H. Circ hole w/78 bbl wtr. PT csg, failed. Establish injection into Dakota perfs. SDON.
- 7-16-96 Load tbq w/21 bbl wtr. Establish injection into Dakota perfs. Plug #1: pump 46 sx Class "B" cmt below cmt retainer into Dakota perfs, pump 5 sx Class "B" cmt on top of cmt retainer, TOC @ 6193'. TOO H to 5469'. Plug #2: pump 13 sx Class "B" cmt @ 5298-5469'. TOO H. TIH, perf 3 sqz holes @ 3558'. TOO H. TIH w/4 1/2" cmt retainer, set @ 3494'. TOO H. Load csg w/wtr. TIH, PT csg to 500 psi, OK. Establish injection. Plug #3: pump 44 sx Class "B" cmt below cmt retainer outside 4 1/2" csg @ 3458-3558', pump 7 sx Class "B" cmt above cmt retainer, TOC @ 3402'. TOO H to 1944'. Load hole w/wtr. Plug #4: pump 42 sx Class "B" cmt @ 1390-1944'. TOO H to 851'. SDON.
- 7-17-96 TOO H. TIH, perf 3 sqz holes @ 890'. Establish injection. TOO H. TIH w/4 1/2" cmt retainer, set @ 851'. Establish injection. Plug #5: pump 115 sx Class "B" cmt below cmt retainer outside 4 1/2" csg @ 600-890', pump 23 sx Class "B" cmt above cmt retainer, TOC @ 548'. TOO H. TIH, perf 3 sqz holes @ 368'. TOO H. Establish circ down csg & out bradenhead. Plug #6: pump 194 sx Class "B" cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. SDON.
- 7-18-96 ND BOP. Cut off WH. Pump 5 sx Class "B" cmt to fill 4 1/2" csg & 4 1/2" x 9 5/8" csg annulus. Install dry hole marker w/10 sx Class "B" cmt. RD. Rig released. Well plugged and abandoned 7-18-96.

14. I hereby certify that the foregoing is true and correct.

Signed *Regan Starnes* Title Regulatory Administrator Date 7/25/96

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

CONDITION OF APPROVAL, if any: _____

APPROVED

JUL 26 1996

DISTRICT MANAGER

NMOC