



UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT



FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Amoco Production Company

3. Address and Telephone No.

200 Amoco Court Farmington 326-9219

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

NE/NE Section 19-29N-16W

5. Lease Designation and Serial No.

I 89 IND 58

6. If Indian, Allottee or Tribe Name

Navajo

7. If Unit or CA, Agreement Designation

8. Well Name and No.

NAVAJO #10

9. API Well No.

10. Field and Pool, or Exploratory Area

Hogback

11. County or Parish, State

SAN JUAN-NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing

☒ Other Re-plug

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attached re-plug procedure for this well. Requested by Linda Taylor (BIA).

14. I hereby certify that the foregoing is true and correct

Signed

BS Shaw

Title

Enviro. Coordinator

Date

11-3-99

(This space for Federal or State office use)

Approved by

/s/ Joe Hewitt

Title

Date

NOV -5

Conditions of approval, if any:

Navajo Well Work Procedure

Amoco Navajo Hogback #10

Version: Navajo10.doc
Date: October 20, 1999
Budget: Servicing PXA
Work Type: Drill out and replug

Objectives:

1. Repair road washout & level spot for service unit
 2. Move in service unit, pit & pump
 3. Install BOP & drill out to TD 600' + or-
-

Pertinent Information:

Location:	990' FNLoF NE1/4 Cor. x 990'FWL of NE1/4 Cor.	Horizon:	
County:	San Juan	API #:	
State:	New Mexico	Engr:	Buddy Shaw
Lease:		Phone:	W-505-326-9219
Well Flac:			M- 505-320-0401
			P---505-326-8261

Economic Information:

APC WI:	100%	Prod. Before Repair:	N/A
Estimated Cost:	\$7,250.00	Anticipated Prod.:	N/A
Payout:	N/A		
Max Cost -12 Mo. P.O.			
PV15:			
Max Cost PV15:			

Formation Tops: (Formation tops)

:Estimated TD 610'

*(Estimated)

Bradenhead Test Information:

Test Date: Tubing: NA Casing: 4.5 BH: 0 psi

Time	BH	CSG	INT	CSG
5 min				
10 min				
15 min				

Current wellbore info: 7" SC Surf-TD, 4 ½"

Current inj info: Off set information 60 yards WSW

0. One call and repair road for service unit

1. MIRUSU..

2 Install Bop, drilling & circulating equipment

3. Pick up bit and 2 3/8" tubing

4. Drill out 4.5" casing to TD (recording all cuttings and data incountered)

5. Rig up Cementers and fill 4.5" casing ffrom TD to surface.

7 Turn all information to Buddy Shaw

Vance Norton

Work - 505-326-9211

Mobile- 505-320-6677

Fax - 505-326-9262

Cost Breakdown:	Road & Dirt	\$ 650.00
	Rig (3 days)	\$ 4,650.00
	Welder	\$ 250.00
	Water Trucking	\$ 400.00
	2 3/8' Work Str	\$ 450.00
	Rental, Misc.	\$ 350.00
	Cont. (15%)	<u>\$ 500.00</u>
	TOTAL	\$ 7,250.00