

New Mexico Oil Conservation Commission

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

March 10, 1959

Mr. Walter A. Martin
Sierra Del Oro, Inc.
523 Third Street NW
Albuquerque, New Mexico

Re: Well #1, SE¹ SW¹
Sec. 14-29N-11W
San Juan County, N.Mex.

Dear Mr. Martin:

We have received a request for release of plugging bond for subject well.

We cannot release the bond for the following reasons: 1. The surface casing has water standing near the top, which indicates the well to be producing water. 2. Gas is bubbling through the water indicating the well to be producing gas, and 3. The location has not been "cleaned up".

This well must be re-plugged with cement plugs to stop all production of gas and water as provided by Rule 202 of the Rules and Regulations.

If we can be of assistance, please contact us.

Yours very truly

A. R. Kendrick
Engineer, District #3

ARK:ke

New Mexico Oil Conservation Commission

1900 RIO BLANCO ROAD

ALBUQUERQUE, NEW MEXICO

MARCH 10, 1937

Mr. Walter A. Martin
State Oil Co., Inc.
223 Third Street NW
Albuquerque, New Mexico

Re: Wood #1, SW 2 1/4
Sec. 14-29-11W
San Juan County, N.M.

Dear Mr. Martin:

We have received a request for release of plugging bond for subject well.

We cannot release the bond for the following reasons: 1. The surface casing has water standing near the top, which indicates the well to be producing water. 2. Gas is bubbling through the water indicating the well to be producing gas, and 3. The location has not been "cleaned up".

This well must be re-plugged with cement plugs to stop all production of gas and water as provided by Rule 202 of the Rules and Regulations.

If we can be of assistance, please contact us.

Yours very truly

A. E. Kendrick
Engineer, District #2

AKK:ms