

7-10-74

Roy L Cook  
Gale no 1  
M sec.13 T 29 R11 W

Moved rig on well made trip too Farmington for cat line

7-11-74

went to farmington for 12 elivortors rigged up to pull 1" tubing.  
pulled 77 jt. 1" 1617 ft. had perft. jt on bottom

7-12-74

Ran 4 $\frac{1}{2}$  bailor to bottom of well 1636ft. bailed 7 bailors full.  
riged up for running 2/3/8 tub. ran 8 jt. tub put giberson packer  
Packer would only go down 210 ft.

7-13-74

Riged up drilling tools and rented swedge from McNutt Tool co.  
Pipe seemed to be either egged shaped or bent went in with swedge.  
to see if pipe could be opened up.  
swedge got stuck in hole Put 5 Gal Descal fuel on swedge

7-15-74

went too Farmington for fishing tools tried to get swedge out  
Jarring on Swedge.

7-16-74

riged up lines to pull on swedge pulled rear gay lines loose  
and bent the derik. worked on rig

7-17-74

working on rig.

7-18-74

working on rig tried to jack swedge out with 2/3/8 tub tub only  
stretched 4 $\frac{1}{2}$   
pulled out 2/3/8 tub ran full opening mahew drill pipe with set  
long stroke jars.

7-19-74

jarring on swedge-----

7-20-74 put 5 gal 33% hlc acid on swedge

7-22-74 Jarring on swedge 72 Hr.

7-23-74

7-25-74

7-26-74-----

7-27-74 Put two 35 ton Jacks to try to pull swedge pulled  
drill pipe inko apart

7-29-74

fished out drill pipe

rented 2/7/8 drill pipe ran in hole

8-1-74 jarring on pipe and swedge.

no luck.

8-2-74

trying to get swedge out.

8-6-74

jarring on swedge

8-7-74

pulled drill pipe from off the swedge . decided to mill over  
swedge . ran water line from ditch to circulate water,  
pump broke down went to Farmington hunting parts ,  
had to have gear made at san juan machine shop did not work.  
bought new pump to circulate water.

8-13-74

milling on swedge.

8-14-74

milling on swedge.

milling on swedge 8-15-74

8-16-74

cont.

