

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.  
Indian Allotted  
#14-20-603-5036  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER Depleted Reference 14-20-603-5036  
3162.3-4 (016)

2. NAME OF OPERATOR  
Texas Eastern Developments, Inc.

3. ADDRESS OF OPERATOR  
P. O. Box 2521 Houston, TX 77252-2521

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

14. PERMIT NO. 15. ELEVATIONS (Show whether on the well or on the resource area)  
5189.97' GR

Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

# 27 Shiprock #1 #6

10. FIELD AND POOL, OR WILDCAT

Shiprock-Gallup

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA

Sec. 17, T29N, R18W

12. COUNTY OR PARISH 13. STATE

San Juan NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>	(Other)	<input type="checkbox"/>		

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well Data

Spud 4/24/61 TD 115' Hole Size 6 3/4" Casing 5 1/2" @ 95' cmt'd w/ 5.0 sx.  
Casing Recovered: Size 0 Amount 0 ft.  
Producing interval: 95' - 115'  
Method of Plugging: Halliburton Pump  
Type Cement: Portland w/8% Bentonite, slurry wt. 13.3 ppg, slurry vol. 1.82 cu ft/sx  
Remove rods, pump and tubing.  
1st stage cement: Squeeze 2.0 cu ft, set plug 115' to surface w/ 15.0 cu ft.  
Top cement at 0' GL.  
2nd stage cement: set plug —' to surface w/ —' cu ft cement.

Dates

Notice of intent to plug approved: JAN. 28, 1987  
Well plugged: MARCH 12, 1987  
Land Restoration: MARCH 19, 1987  
Marker set: MARCH 26, 1987  
Land seeded:

APR 20 1987  
OIL CON. DIV.  
Approved as to plugging DIST. 13  
Liability under bond is retained until  
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED H. N. Hinds

TITLE

Drilling Superintendent

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

APR 15 1987

John S. Keller  
AREA MANAGER  
FARMINGTON RESOURCE AREA

\*See Instructions on Reverse Side