

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Federal <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Cornell
3. Address of Operator Box 990, Farmington, New Mexico - 87401	9. Well No. 4 (P&A)
4. Location of Well UNIT LETTER C 920 FEET FROM THE North LINE AND 1720 FEET FROM THE West LINE, SECTION 14 TOWNSHIP 29N RANGE 12W NMPM.	10. Field and Pool, or Wildcat Fulcher Kutz P. C.
15. Elevation (Show whether DF, RT, GR, etc.) 5628' GL	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged and abandoned as follows:

Spotted a 25 sack cement plug through tubing on bottom to cover open hole, pulled tubing.

Shot 5 1/2" casing off at 1150', spotted a 30 sack cement plug on casing stub at 1150', pulled casing.

Spotted a 25 sack cement plug at base of surface casing (25').

Placed a 10 sack cement plug at surface w/a 4' x 4" P & A marker.

A sundry notice will follow when location is cleaned up.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed F. H. WOOD TITLE Petroleum Engineer DATE 9-30-69

APPROVED BY Emmy Charles TITLE Sup. Dist. III DATE 10-2-69
CONDITIONS OF APPROVAL, IF ANY: