

GOVERNOR

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

DIVISION APPROVED PLUGGING PROGRAM

J. Warren Miller
Palmer #1
300' FNL, 300' FEL
A-17-T29N-R13W, and Juan County, N.M.

Downhole Equipment
Unknown
Presumed T.D. 1291'

- 1. Locate well.
- 2. Enter and clean out/or drill out to 1291'.
- 3. Set cement plug inside and outside casing, if present, from T.D. to 900', to isolate Pictured Cliffs formation.
- 4. Set a cement plug inside and outside casing, if present, from 400' to surface, to isolate Farmington S.S. formation.
- 5. Set dry hole marker.
- 6. Clean and restore location to original condition.
- 7. All plugs shall be of Class A, B, or C neat cement and may be accelerated by up to 3% CaCl2.
- 8. All plugs are to be separated by gel mud of minimum nine pounds per gallon.