




Blake #1

Landowner is Lloyd
Mascaranas

Mother is Rose works @
First National Bank

COUNTY San Juan STATE NEW MEXICO
SEC. 9 T. 29N R. 13W
FIELD OR AREA LOCATION SE SW
LEASE Umberhour WELL NO. 1
COMPANY San Juan Petr. Co. SPD. 12-2-27 COMPLETED 5- -28
ELEV. 5301' T. D. 3005' P. B. _____
CASING _____
SHOT OR ACID _____
PERF. _____
I. P. _____
PRODUCING FORM. _____
PRODUCTIVE DEPTH OR INTERVAL _____

REMARKS:

Abandoned



TONEY ANAYA
GOVERNOR

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

DIVISION APPROVED PLUGGING PROGRAM

J. Warren Miller
Umbenhour #1
N-09-29N-13W, San Juan County, N.M.

Downhole Equipment
Unknown
Presumed T.D. @ 3005'

1. Locate well.
2. Set a cement plug inside and outside casing, if present, from T.D. to 2600', to seal off Cliff House formation.
3. Set a cement plug inside and outside casing, if present, from 1300' to 1100', to seal off Pictured Cliffs formation.
4. Set a cement plug inside and outside casing, if present, from 400' to surface, to seal off Farmington S.S.
5. Set dry hole marker.
6. Clean and restore location to original condition.
7. All plugs shall be of Class A, B, or C neat cement and may be accelerated by up to 3% CaCl_2 .
8. All plugs are to be separated by gel mud of minimum nine pounds per gallon.

