

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

1-89-IND-56

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐  
2. NAME OF OPERATOR Continental Oil Company  
3. ADDRESS OF OPERATOR 152 North Durbin, Casper, Wyo. 82601  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface 660' FNL, 1980' FNL (Unit Letter C)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rattlesnake Cove

9. WELL NO.

146

10. FIELD AND POOL, OR WILDCAT

Rattlesnake - Penn. BCD

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 11, T29N, R19W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5262' RB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well History: TD 6695', Surface casing, 13 3/8", 48#, H-40 set at 310' and intermediate casing, 9 5/8", 36#, J-55 set at 4520'. Production casing, 7", 23#, J-55 set at 6561'. Open-hole 6561-6695'. Well Status: Gas flowing.

We propose to plug the well as follows:

Spot 100' cement plug from 6250-6350' in 7" liner.

Spot 25' plug in surface casing.

Set 10' length of 4" pipe in surface plug so that it projects at least 4' above ground level.

Top of 4' will be capped and a marker attached or welded on pipe.

200' cement plug 6300-6500'

150' " " 5400-5550'

100' " " 4200-4300'

30' surface plug with marker.

USGS(6) NMOGCC(2) File(2)

18. I hereby certify that the foregoing is true and correct

SIGNED *Elmer L. Phillips*

TITLE Administrative Supervisor

DATE 8-18-71

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side